## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For comers in

5. Private Claims

Dickinson		Located In:				Corner Code #
(County)						
1. Public Land Survey		Т		R		
·		Т		R		-
		T		R		
2. Property Controlling	S 2	21 T	44N	R.	30W	F8
in Section	S	<u>?1</u> T	44N	R	30W	14
	s—	T		R		(0)
3. Miscellaneous	s—	${T}$		R		
Property in Sec.	s			R'		

Register of Deeds Stamp & File Number

I, Stephan J. Szyszkoski, in a field survey on 14 07/29/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, a re-established, monumented, recovered, found as expressed below:

1 2 6 5 4 3 2 1 1 2 2 5 5 6 6 6 18 17 16 15 14 13 6 6 6 6 7 6 6 7 7 19 20 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- (F8) Center of Section 21. Not established in the original survey.

(14-Sec. 21) South 1/16 corner between Sections 21 and 22. 1991 - Established by Edward Kazianka RLS midway and on line between Section corner 1/4 mile to the south and the position of the Quarter corner 1/4 mile to the north. Set 4" alum. cap on a 1" iron pipe. Maple 11" N74E 13.93', W.Birch 11" N07W 14.26', Aspen 7" N83W 3.81'.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F8) Established the corner at the intersection of straight lines connecting opposite 1/4 corners of record. The 1/4 corner to the south is that recorded by the undersigned, and not that corner approved by the Dickinson Co. Survey Peer Group in 2005. The 1/4 corner to the east was reestablished in 1991 by Surveyor Edward Kazianka, RLS.

(14-Sec. 21) Found the 1991 monument in good condition, as described, substantially at the record position, and at record bearing and distance from the 1991 witnesses. The Maple NE and W.Birch NW are in good condition with overgrown blazes and overgrown measuring nails. The Aspen NW is dead and down. Accepted the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Sugar N25E 26.3' mrkd "C1/4 BT" 14" Sugar S42E 32.6' do 10" Sugar S16E 28.8' do 20" Sugar S84W 19.2' do Set sq'd cedar post adjacent. Bearings are magnetic.

(14) Fd. 1"ID I.pipe with 4" alum. cap stamped to identify the corner (RLS 14765)

Set measuring nail with MDNR tag in the side of:

11" Maple N73E 14.0' old blaze 1991 BT

12" W.Birch N06W 14.3' do do

4" Cherry S48E 13.2' mrkd "1/16S BT"

7" Maple N44W 22.9' do

Set sq'd cedar post adjacent.

Bearings are magnetic.

Signed by Surveyor's Michigan License No. 33986

Date

12/09/2010

For the Michigan Department of Natural Resources and Environment, Forest Management

FORM APPROVED BY MICHIGAN STATE BOARD C

Oct. 1971 Oct. 1977 14, 1975 Fixed Jan., 1983 Rervised Oct., 1995

STEPHAN J

SZYSZKOSKI

LAND

is SURVEYOR

16553 16544