LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Gladwin		Lo	ocated li	า	Corner Code #	
(County)						
1. Public Land Survey		Ţ -	18N R	1E	1-4	
Property Controlling in Section Miscellaneous Property in Section	s s s	T - T -	F			Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat: A B C D E F G H I J K L M					
5. Private Claims:					2 6 6 5 4 3 2 1	
I, <u>Craiq W. McVean</u> , in a field survey on <u>Nov. 14</u> , 20 <u>11</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.						3 4
A. Description of original	monumer	it and	accesso	ories and	d/or subsequent rest	oration:
<u>I-4</u> – 1846 – GLO – J. Mullett – Set ¼ Post 1) Maple 10" - S63°E 17 L.						- 2006 – Rec. Survey – L. S4, p. 157 – R. G. Strejc – Mon. Box Center Michigan Hwy. M-61.

- 2) Hemlock 8" S70°W 30 L.
- 1930's CCC Notes South 102:00 Set Random 1/4 post
- 1957 MDOT M-61 Rd., Plans 1/2" Iron rod in center M-61. Distance to 'G4' - 5279.28'; Distance to 'K4' - 5281.07'
- 1978 Rec. Survey L. 1, p. 906 J. Meyers Fd. capped iron.
 3) N50°W Tele. Riser 85.55'; 4) N45°E 10° Oak 88.25';
- 5) South ROW Marker 75.00; 6) S30°W Power Pole 81.40'
- 1988 Record Survey L. 2, p. 371 J. Meyers Same description and witnesses as 1978 Survey.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 1-4 1/4 Corner common to Sec. 10 & 11, T18N, R1E Fd. 1/2" x 0.8' long rebar with unreadable plastic cap in Monument Box in physical centerline of E-W Bit. Rd. (M-61). Removed ½" capped iron and dig down in monument box and find 1" iron bar down 1.1'.

 1" iron bar was 0.03' North and 0.11' East of ½" CIR. Two-track road to the North. No GLO evidence. Measured grid bearing distance of N89°41'18"W 5278.91' (5279.28' – MDOT) to 'G4' and S89°13'14"E 5282.01' (5281.07' – MDOT) to 'K4'. 1" iron bar in Mon. Box accepted as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-4 - Raised 1" iron bar with stamped 2 1/2" DNR brass cap on 5/8" x 6" long rebar in Monument box.

N40°E 122.90' to set nail & tag in NW side 22" Oak N40°W 79.81' to set nail & tag in SW side 12" Scotch Pine S18°E 117.99' to set nail & tag in SW side twin 14" & 16" Oak S20°W 82.65' to set pk nail & tag in W side Power Pole(new) South 75.24' to fd. 3/8" I.D. iron pipe (#5?)

Signed by:

Surveyor's Michigan License No.:

39088

MICHIGA CRAIG W. **McVEAN** PROFESSIONAL URVEYOR No. 39088 A OFESSION