

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office }
Gogebic County } ss.

For corners in
Gogebic
(County)

Located In: Corner Code 44

Received for record the
16 day of SEPT
A. D. 1994 at 4:10 o'clock
P m., and recorded in
Liber 5 of CORNER
on page 141
Ramona Collins, Deputy
Register of Deeds

1. Public Land Survey T 47N R 47W M-13
T 47N R 46W A-13
T 46N R 47W M-1
T 46N R 46W A-1
2. Property Controlling S 46N R 47W M-1
in Section S 46N R 46W A-1
3. Miscellaneous S 46N R 46W A-1
Property in Sec. S 46N R 46W A-1

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
Township corner common to Sections 36, 31, 1 & 6, T47-46N,
R47-46W

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John R. Garske, in a field survey on June 20, 1994,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

On September 3, 1847, William A. Burt set a hemlock post at town corner from which a Y. Birch
16" bears S25°E, 25 links and a hemlock 18" bears S52°W, 21 links.

No original evidence found due to road construction.

PEER GROUP Approved
Richard L. Dralun 9/14/94

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 2' long x 2" diameter pointed iron pipe 4" below road surface. Pipe was found to be bent
and in poor condition. I carefully dug up corner and replaced it at the mark the point of the pipe
left in our excavation. I accepted the corner as being true due to the substantial pipe found, at the
proper location within the intersection of South Davis and East Pioneer Road. This pipe has been
used and accepted as the section corner for many years.

After restoring the corner position, I upgraded it as noted below to state and county specifications.
Corner was found 0.50 feet west of the approximate centerline of South Davis Road and 1.50 feet
north of the approximate centerline of East Pioneer Road.

Research record form on file with County Register of Deeds Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced found bent iron pipe with a 1" x 36" iron pipe with a 2 1/2" brass cap with a 2" stem on
top of pipe set in anchoring cement 3" below road surface. I established the following bearing
trees and reference objects: A reference monument consisting of a 2 1/2" x 30" aluminum pipe
with a 3 1/4" aluminum cap stamped to indicate the corner position as follows: S47°E, 48.12 feet
with a steel sign post 1.71 feet away; 14" R. pine - N20°E, 108.44 feet; P. pole #5 - S/96 - S45°E,
39.82 feet; P. pole #1 - 94/93 - S52°W, 41.87 feet.

Signed by John R. Garske
Surveyor's Michigan License No. 28410

Date 8/31/94
FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983