SECTION

Surveyor's Michigan License No.

LIBER 619 MONTCALM COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDS

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN GRATIOT COUNTY RECORDED

	corners in ratiot	Located In:	Corner Code #			11 JAN	2000	9:36 (4. M.	
•	(County)	— Elba Township				JAN	ET K. I	nauts		
1. F	ublic Land Survey Se	ec. 13,14 T 9N R 1W 23,24 T R	K7				STER O		6	
ir 3, N	Property Controlling n Section Miscellaneous Property in Sec.	T R S T R S T R S T R S T R		Registe	er of D	eeds S	Stamp (& File I	Numbe	er
4. L 5. P	ot No, Re	corded Plat			A B	C D	E F (э н	IJK	. L
· ·			1	2	6	5	4	3	2	1
	m: 11: a	(D) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		3				<u> </u>	ļ <u> </u>	
do h	ereby certify that under	requirements of P.A. 74. Michigan	P.A. of 1970, the corner points ment	oned -	7	8	9	10	11	12
curre	nt manual of survey insi	tructions of the United States Dep	s and rules therefore as required in partment of the Interior, Bureau of	n the Land 6	18	17	16	15	14	13
abov	e were in conformance i	with the rules of the Michigan Bo	corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decre	eofa	19	20	21	22	23	24
expre	t of Law; established essed below:	i, re-established, monumented,	re-monumented, recovered, found	1 as 8	19	20	21			24
NOT			and range, may be recorded	10 11	30	29	28	27	26	25
•	on this certificat	e. '		12	31	32	33	34	35	36
В.	October 1875, S.S. Has Stone S62°W 33 Oak S56 ¼ °E Oct. 11, 1978, Jerry L. fd. 1/2° pipe in Mo Nov. 1 1978, Jerry L. Fd. 1/2" pipe in M Description of corner Searched at the a of the centerline. All feet in diameter and the corner K-08 is 264 Description of monum Found 1" iron pipe	Set a post cor. Sect. 13,14, 23 & 24 Elm 5 S41 E 12 Do 6 N30 W56 October 1875, S.S. Hastings, Deputy Surveyor, Stone S62*W 33 ½ Oak S56 ½ *E 1.49 ½ Oct. 11, 1978, Jerry L. Jones, Recorded Survey, Liber 417, Page 601 (d. 1/2* pipe in Mon. Box N. 44*- spike in P.P. (questionable) E. 28*- E. end culv. W. 10*- CL road No. 44*- spike in P.P. (questionable) E. 28*- E. end culvert W. 1.0*- CL road Description of corner evidence found and/or method applied in restoring or reestablishing corner: Searched at the apparent location of the corner and found a 1* x 2* iron pipe 0.25* below the surface in a monument box 0.85* east of centerline. Also, found small pieces of rotted wood and two pieces of broken glass 2.90* below surface. Excavated a hole to eet in diameter and three and a half feet deep, found nothing else. Th distance to the ½ corner K-06 is 2656.47 feet and the distance of centerline of monument for corner and accessories established to perpetuate locating the position of the corner: Found 1* iron pipe in monument box, 0.85* east of centerline, set remonumentation pipe.								le two
	Nail and Top Cen Top Cen	tag # 30104 NW side power potag # 30104 S side 20" cottonviter 60" concrete culvert (West iter 60" concrete culvert (East iter 60" concrete culver (East iter	wood West 63.90 fee End) S85°W 32.00 fee End) S72°E 33.40 fee	t t						
This	corner is accepted as	the best available evidence of	the position of the original corner	•						
٥.	$\cdots \cap \mathcal{M}$	\		1 1						E

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197: