

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Houghton</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 35W	B7
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S 19 T 51N R 35W	11
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkowski, in a field survey on B7 05/03/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B7) Quarter corner common to Sections 18 and 19. 1966 - Reestablished by Billy D. Buckler RLS #8887 on line and by single proportionate measure between two Section corners. Set 1" pipe with 4" aluminum cap. 14" Hard Maple N52E 13.2', 14" Hard Maple S30W 40.7'.

(11-Sec. 19) Southwest 1/16 corner, Section 19. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B7) Found the 1966 monument in good condition and at record bearing and distance from the remaining NBT Sugar, S30W 40.7' with scribing visible. Found the position of the monument to be 0.95' south and 5.6' west of the proportionate position intended in 1966 and accepted same as a careful and faithful reestablishment of the position of the original corner.

(11-Sec. 19) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B7) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
 15" Sugar S34W 41.0' old marks 1966 NBT
 6" Maple N73W 10.5' mrkd "1/4S NBT"
 6" Maple N33E 6.35' do
 9" Sugar S77E 28.2' do
 Set sq'd spruce post adjacent.
 Bearings are magnetic.

(11) Set 1"IDx32" I.pipe with plastic cap stamped "MICH DNR PS 33986".
 Set measuring nail with MDNR tag in the side of:
 11" Maple S40E 18.15' mrkd "1/16S BT"
 9" Y.Birch S24W 15.5' do
 9" Maple S68W 34.15' do
 6" Balsam N13W 3.75' do
 Set sq'd cedar post/location poster adjacent.
 Bearings are magnetic.

Signed by Stephan J. Szyszkowski
 Surveyor's Michigan License No. 33986

Date 06/02/2011



For the Michigan Department of Natural Resources, Office of Land and Facilities