## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	_ Located In:	Corner Code #	16 a	
1. Public Land Survey	T 51N R 36W T R	D7	s	
2. Property Controlling in Section	S T R S 19 T 51N R 36W S T R	3 00 20		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4. Lot No. , Rec 5. Private Claims	orded Plat		A B C D E F G H I J K L	M
i, Stephan J. Szyszkoski , in that under requirements of P.A.		/02/2010 do hereby state	4 - 7 8 9 10 11 12	_
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with			rvey 5 17 16 15 14 13	
			shed, B 19 20 21 22 23 24 9 10 30 29 28 27 25 25	
NOTE: Not more than 2 corners on this certificate.	ers, all in the same town and range	e, may be recorded	11 2 31 32 33 34 35 36	-

A. Description of original monument and accessories and/or subsequent restoration:

(D7) Quarter corner common to Sections 17 and 20. 1848 - Established by S.W. Higgins Deputy Surveyor midway and on the Section line between Section corners 40.31 chains east and west. Set post. Balsam 10" S40W 9 links, Balsam 8" East 3 links.

(3-Sec. 19) North 1/16 corner between Section 19 T51N-R36W and Section 24 T51N-R37W. 1992 -Established by the undersigned midway and on line between corners A7 and A8. Set 1"IDx36" I.pipe with 4" alum. MDNR cap. 8" Sugar N23E 16.7', 12" Sugar N55W 11.5', 8" Hemlock S50E 27.0', 8" Sugar S36W 54.1'. Corner lies 3' NW of the NW edge of a gravel road.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D7) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner position midway and on the Section line between monumented Section corners 2642.07' east and west.

(3-Sec. 19) The 1992 monument was destroyed in Aug. 2010 by heavy equipment while making improvements to the adjacent road. Remonumented the corner in the 1992 position which was found clearly marked by evidence in the soil. Found three of the four 1992 witnesses at record bearing and distance.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 15" Sugar N10W 22.85' mrkd "1/4S NBT" 4" Sugar N55E 20.45' do 5" Sugar South 3.95' do 14" Maple S84W 22.45' do Set sq'd cedar post adjacent. Bearings are magnetic.

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: old marks 8" Sugar N26E 16.7' 1992 BT 10" Sugar N53W 11.8' do do 7" Sugar S38W 54.3' overgrown blazes do 5" Hemlock S47E 30.0' mrkd "1/16S BT" Set sq'd cedar post adjacent. Bearings are magnetic.

Signed by Surveyor's Michigan Ligense No.

For the Michigan Department of Natural Resources and Environment, Forest Manageme

01/06/2011

SZYSZKOSKI

LAND

ISSURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD

16560

16559

ed Jan., 1983 Rervised Oct., 1995