LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

			1		
Houghton	Located In:	Corner Code #			
(County)					
1. Public Land Survey	T 51N R 36W T 51N R 36W	M1 M2	63 13		
2. Property Controlling in Section	S T R S T R		ä	*	
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds	Stamp & File Number	
4. Lot No. , Rec 5. Private Claims	corded Plat	cā dej		F G H I J K L	_
above were in conformance with r instructions of the United States I	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require Department of the Interior, Bureau of La orner points mentioned in lines 3, 4 and	ed in the current manual of survey and Management or by a decree o	y 5	9-10-11-12	<u> </u>
the rules of the Michigan Board re-established, monumented, recove	of Land Surveyors or by a Decree	of a Court of Law; established	9 19 20 2	3 22 23 24	<u> </u>
on this certificate.	ers, all in the same town and range,		10 30 29 2 11 12 31 32 3	3 34 35 36	5
 A. Description of original me 	onument and accessories and/or s	subsequent restoration:			

- (M1) Northeast township corner of T51N-R36W. Common to T51-52N and R35-36W. 1982 Reestablished by K.L.Sackett RLS by double proportionate measurement between adjacent corners and land calls. 1"IDx32" I.pipe with 4" alum. cap. 9" Hemlock S58E 19.3', 10" W.Pine N70W 2.6', 4" Maple S04W 15.2'.
- (M2) Quarter corner common to Section 1 T51N-R36W and Section 6 T51N-R35W. 1982 Reestablished by K.L.Sackett RLS by proportion between Section corners north and south. Set 1"IDx32" I.pipe with 4" alum. cap. [?]" Sugar S12W 36.8', [?]" Y.Birch N39E 21.0', [?]" Sugar N29W 17.0'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.
- (M1) Found the 1982 monument in good condition and at record bearing and distance from two 1982 NBTs: The Hemlock SE and the Maple SW are in good condition with overgrown blazes. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- (M2) Found the 1982 monument in good condition and at record bearing and distance from two 1982 NBTs: The Sugar SW and the Sugar NW are in good condition with overgrown blazes. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MI) Found 1"ID I.pipe with 4" alum. MDNR cap.	(M2)
Set measuring nail with MDNR tag in the side of:	Set m
12" Hemlock S58E 19.4' old blazes (1982 NBT)	18" S
5" Maple S05W 15.3' do do	4" Su
5" Maple N23W 8.7' mrkd "S36 NBT"	5" Y.
6" Maple N67E 16.35' "S31 NBT"	6" Su
Set sq'd cedar post adjacent.	Set s
N=231470.290, E=7862309.507	N=230

Found 1"ID I.pipe with 4" alum. MDNR cap. easuring nail with MDNR tag in the side of: ugar S17W 37.75' old blazes (1982 NBT) gar N28W 17.15' do do mrkd "1/4S NBT" Birch N66W 21.85' gar N78E 18.55' q'd cedar post adjacent. 648.810, E=7862290.432

Bearings are magnetic. Coordinates are MCS83 in meters.

Surveyor's Michigan License No. 33986

Date

02/07/2013

FORM APPROVED BY MICHIGAN STATE BOARD

For the Michigan Department of Natural Resources, Forest Resources Division

LAND SA 14, 1975 Revised Oct., 1995

STEPHAN SZYSZKOSKI

LAND

SURVEYOR