## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

i

Houghton (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 51N R 36W T 51N R 36W	K2 L3	71 <b>5</b> 75
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous Property in Sec.</li></ul>	S T R S T R		*
4. Lot No. , Red 5. Private Claims ,	corded Plat		Register of Deeds Stamp & File Number  1 A B C D E F G H I J K L M 2 6 5 5 6 7 7 8 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1
above were in conformance with a instructions of the United States I a Court of Law and /or that the	74, Michigan P.A. of 1970, the corner regulations and rules therefore as required Department of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	red in the current manual of survey and Management or by a decree or d 5 above were in conformance with	6 18 17 16 15 14 13 7 8 19 20 21 22 23 24
on this certificate.	ers, all in the same town and range onument and accessories and/or		9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

- (K2) Quarter corner common to Sections 1-2. 1970 A.O.Enger RLS remonumented the corner in the original position at record bearing and distance from an original BT W. Pine 24" S87E 5 links, a stump in good condition with scribe marks "1/4S" and "BT". Set 1"IDx36" I.pipe with 4" alum. cap. Red Maple 6" S38W 5.0', Red Maple 4" N02W 6.0'.
- (L3) Quarter corner common to Sections 1-12. 1970 Reestablished by A.O.Enger RLS by proportionate measurement to the original record between Section corners. Set 1"IDx36" I.pipe with 4" alum. cap. Sugar Maple 10" N25W 12.5', Hemlock 6" S75E 16.0'. Squared and scribed an Oak N5W 3 ft. from corner.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K2) The 1970 monument was recovered in good condition and at record bearing and distance from one 1970 NBT: The Red Maple 4" N02W 6.0' is in good condition with overgrown blazes. The stump of the OBT W. Pine is present at record bearing and distance but all traces of scribing have rotted away. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.
- (L3) The 1970 monument was recovered in good condition and at record bearing and distance from the Hemlock SE and from the Oak N5W, both in good condition. In spite of the 1970 record, the Oak N5W shows no sign of having been squared and scribed (probably due to its vigorous growth). The monument was found substantially at the proportionate position between Section corners and is accepted as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K2) Found 1"ID I.pipe with 4" alum. MI Dept. of onservation cap. Set measuring nail with MDNR tag in the side of:  " Maple N04E 6.2' old blazes (1970 NBT)  2" Maple S61E 9.95' mrkd "1/4S NBT"  " Sugar S10W 14.0' do  " Sugar N71W 7.4' do et sq'd cedar post adjacent. =230695.207, E=7860681.867	(L3) Found 1"ID I.pipe with 4" alum. MI Dept of Conservation cap. Set measuring nail with MDNR tag in the side of:  12" Hemlock S70E 16.0' old blazes (1970 NBT)  16" Oak NO2W 2.95' mrkd "1/4S NBT" do  9" Sugar S03E 6.2' do  6" Maple S63W 10.75' do  Set sq'd cedar post adjacent.
-230093.207, E=7860081.867	N=229872.723, E=7861462.834

Bearings are magnetic. Coordinates are MCS83 in meters.

Signed by Date 02/07/2013 Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN SZYSZKOSKI LAND FORM APPROVED BY MICHIGAN STATE BOARD OF ed Jan., 1983

Revised Oct., 1995