LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	_ Located In:	Corner Code #		
1. Public Land Survey	T 51N R 36W	G4 (GCDB 400540)	** 1	
2. Property Controlling in Section	T 51N R 36W S T R S T R	(GCDB340500)		
3. Miscellaneous Property in Sec.	S T R S T R R S T R R			
4. Lot No. , Recorded Plat Register of Deeds Stamp & File Number				
5. Private Claims			ABCDEFGHIJKL	
above were in conformance with re- instructions of the United States D a Court of Law and /or that the co- the rules of the Michigan Board re-established, monumented, recover	'4, Michigan P.A. of 1970, the corner polegulations and rules therefore as required epartment of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of	if in the current manual of survey of Management or by a decree of above were in conformance with of a Court of Law; established, may be recorded	6 13 17 16 15 14 13 7 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36	
A. Description of original monument and accessories and/or subsequent restoration:				

- (G4) Quarter corner common to Sections 9 and 10. 1983 K.L.Sackett RLS found and accepted a 1"ID iron pipe with Michigan Dept. of Conservation cap set from an original B.T. in 1966 by Billy D. Buckler RLS. 1983 witnesses: 6" Spruce S56°E 11.9', 5" Cedar N22°E 29.5', 8" Hemlock N89°W 15.1'.
- (F5) Quarter corner common to Sections 9 and 16. 1966 Billy D. Buckler RLS remonumented the corner at the position of a found 1" iron pipe set by an unknown surveyor. Set 1"ID I.pipe with 4" aluminum MI Dept. of Conservation cap. 8" Soft Maple West 51.5 links, 8" Soft Maple S72°E 41 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (G4) Found the 1966 monument in good condition and at record bearing and distance from the 1983 witnesses: The Cedar N22°E is standing dead; the Hemlock N89°W is dead and down; the Spruce S56°E is in good condition but bears S65E from the corner (presumably the digits were transposed on the 1983 record). Accepted the monument as a careful and faithful perpetuation of the position of the
- (F5) Found the 1966 monument in good condition and at record bearing and distance from the 1966 witnesses: The Maple West is in good condition with double overgrown blazes; the Maple S72°E is a rotting stump. A 1" iron pipe projecting 3.5' A.G. was found adjacent to the monument. Accepted the monument as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G4) Found 1"ID I.pipe with 4" alum. MI Dept Conservation cap. Set measuring nail with Min the side of: 8" Spruce S65°E 12.5' old blaze (1983 NBT) 7" Y.Birch S02°W 10.2' mrkd "1/4S NBT" 7" Cedar S62°W 22.75' do 9" Hemlock N58°W 15.1' do Set sq'd cedar post adjacent. E= 7857346.095 N= 229221.020	IDNR tag Conservation cap. Set measuring nail with MDNR tag in the side of: 10" Maple N88°W 34 21 old bloom (1966 NEW)

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2012 Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Surveyor's Michigan License No. (33986

Date

03/12/2015

FORM APPROVED BY MICHIGAN STATE BOARD

LAND SURVEYOR

STEPHAN J SZYSZKOSKI

For the Michigan Department of Natural Resources, Forest Resources Division

N. 28, 1971