LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 53N R 35W T R	K13 (GCDB 600100)	
2. Property Controlling in Section	S 36 T 53N R 35W S T R	7 (GCDB700160)	
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No. , Red 5. Private Claims	corded Plat K13 1		A B C D E F G H I J K L M
I, Stephan J. Szyszkoski, in a field survey on 7 10/08/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 2 re-established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and rang	ge, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(K13) Standard Section corner common to Sections 35-36. 1845 - W.A.Burt set post. Cedar 16" N24°E 32 links, Cedar 8" N35°W 37 links. Notes of P.A. & M.C. Larsen for Closing Cor. K1 of T52N-R35W: "1920 - Found old cedar post. 1958 - Set new post along side.". 1966 - Billy D. Buckler RLS: Replaced corner as set by M.C. Larsen, Hancock. Found no original witnesses. 1" pipe with 4" aluminum cap. 14" Cedar N50°E 31.7', 12" Cedar S85°W 31.5', 6" Soft Maple South 17.6'. The 1966 record erroneously describes the Closing Corner as being common to Standard Corner K13. According to the US survey, the Standard Corner is 06 links east of the Closing Corner.

(7-Sec. 36) North 1/16 corner between Section 36 T53N-R35W and Section 31 T53N-R34W. 1922 notes of Fesing show "ced. post" 1322.5' south of Section corner and 1322.5' north of 1/4 corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K13) Found two rotted-off post points at substantial record bearing and distance from the 1966 witnesses, corresponding to the Closing Corner between 1 & 2. Reestablished the position of the Standard Corner K13 3.96' east of the post points, on a line between them and the Township corner. From the position thus established, I found a rotted Cedar stump, no marks, likely the remains of the original BT Cedar N35°W 37 links, at substantial record bearing and distance.

(7-Sec. 36) Found no evidence of prior monumentation at the corner position. Established the position for the corner midway and on the Range line between Section corner 1326.22' north and Quarter corner 1326.22' south. The monument installed leans E'ly 0.2'+/- due to subsurface roots and rock. The top center of the cap marks the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set sq'd cedar post 1 ft. north.	12" Cedar N50°E 29.0' old blazes (1966 wit. tree) 10" Maple S18°W 17.4' do do 15" Cedar N88°W 35.15' do do 10" Spruce S67°E 12.65' mrkd "S1 NBT" 1"ID I.pipe/MDNR cap at Closing cor. N87°W 3.96' Set sq'd cedar post 1 ft. north. Set meas 8" Maple 6" Maple 5" Maple 5" Maple 5" Set sq'd	
----------------------------------	--	--

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum

Date

Coord. Ref.=NGS PID DO8499: N= 221257.624 m. E= 7884435.169 m.

Surveyor's Michigan License No. 33986

Signed by

For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
NO PROFESIONAS SORES OF SORES

FORM APPROVED BY MICHIGAN STATE BOARD O

11/04/2015