## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	_ Located In:	Corner Code #						
1. Public Land Survey	TR							
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S 12 T 43N R 33W S 12 T 43N R 33W S T R S T R	3 2	Registe	er of Deed	ls Stamp	& File	Numbe	,
4. Lot No. , Red 5. Private Claims	corded Plat		A B C	DE	FG	я ј		K L M
	3 08/0	9/2011	2 - 6-					
that under requirements of P.A. above were in conformance with	na field survey on 2 08/0 74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require	9/2011 do hereby state points mentioned in lines 1 and 2 d in the surrent manual of surrent and 2	3	-8-	-	-10-	-11-	- 2
instructions of the United States I	Department of the Interior, Bureau of Lar	nd Management or by a decree of	6 18	-17-	16	-15	-14-	13
a Court of Law and /or that the c the rules of the Michigan Board	orner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	5 above were in conformance with	7	++	++	+		1
re-established, monumented, recover	ered, found as expressed below:	or a Court or Law; established,	T	-20-	-21-	-22	-23-	-24-
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range,	may be recorded	9 10—30— 11 12—31—	29	-33	-27-	-26- -35-	-25 36
A. Description of original m	onument and accessories and/or s	ubsequent restoration:	131			-1-1		

(3-Sec. 12) North 1/16 corner between Sections 11 and 12. Not monumented in the original survey. The GLO plat for this township gives a distance of 20.01 chains to this corner from Section corner K3 and shows the entire mile K3-K5 as 80.04 chains. The Quarter corner on the west line of the Section was not established in the original survey.

(2-Sec. 12) East 1/16 corner between Sections 1 and 12. 2002 - Established by J.H.Moore PS 28423 midway and on a straight line between Quarter corner L3 1311.79' west and Section corner M3 1311.79' east. Set capped rebar.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 12) Established the corner 20.01 chains proportionate distance south of Section corner K3 and on the Section line. This corner is thus 1335.55' south of K3 and 4006.62' north of K5. From the position for the corner, I found a 5/8" rebar, not of record, 43.28' south, which I did not accept as marking the position for the corner.

(2-Sec. 12) Found a 5/8" rebar with J.H.Moore cap substantially at the record position and accepted same as a careful and faithful determination of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.	
Set measuring nail with MDNR tag in the side of	
4" Maple S47E 22.3' mrkd "1/16S BT"	·
8" Balsam S19W 46.3' do	
8" Maple in clump N2OW 50.2' do	
4" Maple N06W 39.4' do	
Set sq'd Cedar post adjacent.	
Bearings are magnetic.	

(2) Fd. 5/8" capped rebar. Set measuring nail with MDNR tag in the side of: 12" W.Birch N68E 9.5' with old blaze 9" Balsam S88W 8.3' do 5" Balsam S37E 16.6' mrkd "1/16S BT" 8" Poplar N48W 13.8' Set sq'd Cedar post adjacent.

signed by Stepher	Stephen I. Synsylval.			09/
Surveyor's Michigan License No.	000	33986		00
For the Mic	higan Department of Na	atural Resources, Foresi	t Management	Division

09/21/2011

SZYSZKOSK LAND SURVEYOR

STEPHAN J

OF MICE

16723

FORM APPROVED BY MICHIGAN STATE BOARD

SAND SA 14, 1975 Rervised Oct., 1995