LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron	_ Located In:	Corner Code #						
(County)								
1. Public Land Survey	T 46N R 33W	C12 (GCDB 200140)						
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S T R S T R	(GCDB 300140)						
4. Lot No. , Rec 5. Private Claims	corded Plat			ter of Deed	s Stamp	& File	Numbe	K L M
above were in conformance with r instructions of the United States D a Court of Law and /or that the cothe rules of the Michigan Board re-established, monumented, recover	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as required Department of the Interior, Bureau of Larorner points mentioned in lines 3, 4 and 1 of Land Surveyors or by a Decree of Pered, found as expressed below:	d in the current manual of survey nd Management or by a decree of 5 above were in conformance with of a Court of Law; established,	6 -18-	29	-16 -21 -28	-10 -15 -22	-11	13-24-
on this certificate.	ers, all in the same town and range,		11 12 31 13	32	-33	-34	35	36
A. Description of original monument and accessories and/or subsequent restoration:								

(C12) Quarter corner common to Sections 31 and 32. 1852 - Established by Francis Houck, Deputy, midway and on the Section line between Section corners 40.12 chains north and south. Set post. Spruce 7" N30°E 14 links, Spruce 6" S21°W 4 links. 1985 - During a survey spanning Sections 28-29-30-32, the original corner was not recovered by K.L.Sackett RLS, for the Michigan Dept. of Natural Resources. Corner was not remonumented at that time.

(E12) Quarter corner common to Sections 32 and 33. 1852 - Established by Francis Houck, Deputy, midway and on the Section line between Section corners 40.155 chains north and south. Set post. Spruce 12" N81°E 20 links, Tamarack 8" S46°W 32 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C12) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2649.32' north and south.

(E12) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2644.25' north and south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(Cl2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.	Set measurin
Set measuring nail with MDNR tag in the side of:	5" B.Spruce
4" Tamarack N48°E 20.95' mrkd "1/4S NBT"	8" Tamarack
6" Tamarack N68°E 19.7' do	10" W.Birch
6" Tamarack S66°E 16.25' do	6" B.Spruce
5" Tamarack S36°E 25.2' do	Squared a 3"
Set sq'd cedar post adjacent.	to the west
E= 7886786.765 N= 174137.141	cap marks th
	E= 7888386.8

(E12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" B.Spruce N87°E 6.1' mrkd "1/4S NBT" 8" Tamarack S14°W 5.3' do 10" W.Birch N86°W 5.2' do 6" B.Spruce N17°W 11.8' do Squared a 3" B.Spruce N55°W 2.0'. The mon. leans to the west about 0.2 ft. The top center of the cap marks the corner position. E= 7888386.896 N= 174101.343

Bearings are magnetic. Coord. Ref.=	Coordinates are	MCS83 in meters,	NAD83 (2011)	Epoch	2010.00 datum
Coord. Ref.=	NGS PID RL0476:	N= 196482.411 m.	E= 7879234.	516 m.	0

Signed by	Stephen	A.	Sasy	lust.
Surveyor's A	lichigan Licenca Na		000	20000

Date 08/06/2015

36

For the Michigan Department of Natural Resources, Forest Resources Division

SZYSZKOSKI LAND SURVEYOR NO. PSHOW889860RS AND 1970 A N D Revision Jan., 197

STEPHAN J

FORM APPROVED BY MICHIGAN STATE BOARD OF