

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

99

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 34W T T	A6 (GCDB 100440)
2. Property Controlling in Section	S 20 T 46N R 34W S S	6 (GCDB 260360)
3. Miscellaneous Property in Sec.	S S	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 6 12/15/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A6) Quarter corner common to Section 18 T46N-R34W and Section 13 T46N-R35W. 1969 - D.L.Lappala,
RLS remonumented the corner from original GLO evidence. Set 2"IDx5' long concrete filled iron pipe
with 3" dia. bronze USFS tablet. 8" Spruce N56°W 9.6'; 7" Cedar N78°W 17.6'; 8" Cedar S42°E 15.7'.
Rec. Liber 3 Page 173, Iron Co. Records.

(6-Sec. 20) Northeast 1/16 corner, Section 20. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A6) Found the 1969 USFS monument as described, in good condition, and at record bearing and
distance from the 1969 NBTs, now all dead and down. Accepted the monument as a careful and faithful
perpetuation of the position of the original corner.

(6-Sec. 20) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A6) Found 2"ID I.pipe with 3" USFS cap.
Set measuring nail with MDNR tag in the side of:
4" Balsam N10°E 14.3' mrkd "1/4S NBT"
3" Balsam S80°E 6.95' do
4" Cedar S13°E 29.9' do
4" Balsam N73°W 17.65' do
Found USFS Boundary sign on 6" post N69W 3.5'
E= 7875645.334 N= 179153.685

(6) Set 1"IDx28" I.pipe with 2" alum. MNDR cap.
Set measuring nail with MDNR tag in the side of:
5" Balsam N05°E 2.6' mrkd "1/16S BT"
5" Maple N88°E 8.0' do
7" B.Spruce S19°E 43.55' do
4" Balsam S66°W 49.35' do
Set sq'd cedar post adjacent.
E= 7878418.017 N= 177907.165

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski Date 05/19/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division