

JACKSON COUNTY
APPROVED LAND CORNER
P.A. 345 of 1990

Chairman Alan L. Scheppelman
Date June 9, 1998

SOUTH 1/4 POST, SECTION 20, WATERLOO TOWNSHIP
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
JACKSON

(County)

Located in:

Corner Code D-9

1. Public Land Survey

1S 2E
T R
T R
T R
T R

D-9



Mindy Reilly - Jackson Co.

CORREM

2128312
Page: 1 of 1
08/11/1998 10:56A
L-1629 P-411

2. Property Controlling
in Section
3. Miscellaneous
Property in Sec.

S T R
S T R
S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

ALAN L. SCHEPPELMAN

JUNE 11

98

I, _____, in a field survey on _____, 19____,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

JOSEPH WAMPLER 39.98 SET QUARTER SECTION POST
NOVEMBER 5, 1825 TAMARACK 8, N46½°W 15 LINKS (9.90')
TAMARACK 4, SOUTH 12 LINKS (7.92')

JOHN K. YOCUM
APRIL 1880

NO DESCRIPTION OF CORNER MARKER
TAMARACK 9, N57½°E 23½ LINKS (15.51')
TAMARACK 10, S86½°W 55½ LINKS (36.46')

SURVEY &
REMONUMENTATION

MAR 13 2000

SECTION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

AN EXTENSIVE SEARCH IN THE SWAMP DID NOT REVEAL ANY EVIDENCE OF AN
EXISTING CORNER. THE CORNER WAS ESTABLISHED BY INTERSECTING THE SOUTH
SECTION LINE WITH THE NORTH-SOUTH 1/4 LINE. SAID NORTH-SOUTH 1/4 LINE
WAS ESTABLISHED BY A LINE FROM THE CENTER OF SECTION RUNNING SOUTH
THROUGH THE ANCHOR POST AT THE 1/8TH CORNER. THIS SOLUTION IS 13.6' WEST
OF A MID-WAY ON LINE POSITION. SET 1" x 60" ALUMINUM PIPE AND CAP
STAMPED "D-9 T1S R2E LS 35998"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" x 60" ALUMINUM PIPE AND JACKSON COUNTY REMONUMENTATION CAP STAMPED
"D-9 T1S R2E LS 35998".
N72°E SET NAIL & TAG 35998 SOUTH SIDE OF 18" TAMARACK 43.56'
EAST SET NAIL & TAG 35998 NORTH SIDE OF 10" TAMARACK 13.39'
S15°E SET NAIL & TAG 35998 EAST SIDE OF 16" TAMARACK 58.22'
N50°W SET NAIL & TAG 35998 SW SIDE OF 16" TAMARACK 60.12'
SOUTH SURVEY MARKER SIGN POST 0.60'



Signed by

Alan L. Scheppelman

Date

07/09/98

Surveyor's Michigan License No. _____

35998