## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970	
For Corners In: Kalkaska Located In Corner Code #	
(County)  1. Public Land Survey  T  Z5N  R  07W  B10  T  R	100
2. Property Controlling in Section S 30 T 25N R 07W 12	
3. Miscellaneous       S       T       R         Property in Section       S       T       R         S       T       R       Register of Deeds Standard St	mp & File Number
4. Lot No: Recorded Plat:	
5. Private Claims:	1 J K L M
I, Craig W. McVean, in a field survey on May 29, 2003 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	1112
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	25
A. Description of original monument and accessories and/or subsequent restoration:  B10 – CSR – Pg. 43 & FB 23, p. 48 – 50 – W. S. Merrill – 1907  Hemlock 18" S76°E 17 L.  Maple 16" S62°W 32 L.  Merrill – 1907  Hemlock 8" N12°W 16 ½ L.  CRAIG W.  McVEAN	
LCERG	PROFESSIONAL SURVEYOR No. 39088
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  B10 - C 1/4 Section 30 - No conclusive evidence of Merrill's position, his BT's are gone. Set 2" Aluminum cap on 5/8" x 34" rebar per standard BLM procedure.  12 - CS 1/16 Corner Section 30 - Set 2' Aluminum cap on 5/8" x 34" rebar per standard BLM procedure.	
Apparent remains of fence intersection N, S & W is 2' ± N & 2' ± E.  Reference Pt. – Set spike in Merrill's stake rotten anchor post remains for down fence 21.2' of '12'. Stake remains fit Merrill's Her accept Merrill's position because review of a 1° blunder in his transgulation notes over the south causing a 45' to 50' error in his d line. Spike in Merrill stake not utilized as c	es N & W – N01°53'W emlock BT. Couldn't f his field notes indicates the Manistee River to distance along the N-S 1/4
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner B10 – 2" Aluminum cap on 5/8" rebar  Set blue carsonite post w/ Loc. tag 1' SE  S64°E 22.31' to set nail & tag in N side 16" Sugar Maple  S36°E 18.05' to set nail & tag in SW side 26" Sugar Maple  West 24.99' to set nail & tag in S side 3" Red Pine  N30°E 42.27' to chiseled 'X' on high point of 1.6' x 2.5' x 1.5'  High granite boulder  N20°E 42.27' to Reference Pt spik	SW e 28" Hemlock (WSM) de Twin 9" Sugar Maple le 11" Sugar Maple ide 11" Sugar Maple
Signed by: Cruice W. Mr. Vean Date: 7/9/2003  Surveyor's Michigan License No.: 39088	