## LAND CORNER RECORDATION CERTIFICATE

For corners in  KAIKASKA  Located in:  Corner Code #  REMONULMENTATION  1. Public Land Survey  T. 27N R. 6W. T. R.		Filing Requir	ement of Act 74, Mich. P.A.	1970
2000 REMONMENTATION 1. Public Land Survey T. 2. R		•	·	SURVEY &
1. Public Land Survey    LATR DW   Land Survey   LATR DW   Land Survey		Located In:	Corner Code #	MEINICHARITA IVII AL
2. Property Controlling In Section S. T. R. A. Miscellaneous Property in Sec. S. T. R.  4. Lot No, Recorded Plat  5. Private Claims  1. Recorded Plat  6. Lot No, Recorded Plat  7. In a field survey on August 22		TR		
5. Private Claims    Received the content of the co	in Section S 3. Miscellaneous S Property in Sec. S	TR TR TR TR		SECTION .
I, RIGENE FARRIER  I, an a field survey on August 22 , 20,00 do hareby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comes points mentioned in lines 1 and 2 above were in conformance with regulations and nutset sheefore an equired in the current menual of aurvey instructions of the United States Department of the Interfor, Bureau of Land Management of vivy a decree of a control the full and of the Michigan Base of the Michigan Base of the Michigan Base of the Michigan Base of a Court of Law; detablished, re-established, monumented, recovered, found as supressed below:  NOTE: Not more than 2 comers, at in the seme town and renge, may be recorded on this contification.  A. Description of original monument and accessories and/or subsequent restoration:  6-3: Sec. Cov. Common to Sass. 5, 6, 7, 8, 8, 727N-RBW, Excelsion Township 1825, GL-D. Resurvey, by George W. Cennon, set spot for corner, Suger 6*, NSTPE, 10 Lks; Herricox 20*: S6DVW, S8 Lks 1979, Survey, by DE. McVam (Co. Survey), Co. Rd. Bb., sed into corner civy 1979, Survey, by DE. McVam (Co. Survey), Co. Rd. Bb., sed into corner civy 1979, Survey, by J. Neison, Liber 2, Pg 301 & 802, Tourd 3/8* pge in 1* jips at corner, accessories are basically seme as 1973 LCRC by J.R. Racidiffs, Liber 1, Pg 323, found 1* pice & added 3/8* pips in 1* jips at corner, accessories are basically seme as 1973 LCRC by J.R. Racidiffs, Liber 1, Pg 323, found 1* pice & added 3/8* pips in 1* jips at corner, accessories are basically seme as 1973 LCRC by J.R. Racidiffs, Liber 1, Pg 323, found 1* pice & corner in centerine and on fence line South, fence pest N35*E, 45.88*; 30* Msple, N35*E, 198, 198, 198, 198, 198, 198, 198, 198				
I, BUSINE FARRIER  in a field survey on August 22 , 20,00 do hareby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with requirement greaters and on female and the formal menual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and of the Michigan Board of Land Surveyors or by a decree of a Court of Law and of the Michigan Board of Land Surveyors or by a decree of a Court of Law and of the Michigan Board of Land Surveyors or by a decree of a Court of Law and of the Michigan Board of Land Surveyors or by a decree of a Court of Law and the Michigan Board of Land Surveyors or by a below:  NOTE: Not more than 2 comers, at in the sems town and range, may be recorded on this certificatio.  A. Description of original monument and accessories and/or subsequent restoration:  6-3: Sec. Cor. Common to Secs. 5. 6. 7 & 8. TZYN-RBW. Excelsion Township 1852, GL.O. Resurvey, by George W. Camon, a step of to corner, Suger 6", NS7"E, 10 Lkr; Herricok 20", S60"W, Bit ks 1979, Survey, by E.B. Dimini (Co. Surveyor) on Co. Rd. Bit., stell inte corner only 1895, Survey, by E.B. Dimini (Co. Surveyor) on Co. Rd. Bit., stell inte corner only 1895, Survey, by E.B. Dimini (Co. Surveyor) on Co. Rd. Bit., stell interest on corner only 1895, Survey, by J. Nelson, Liber 2, Pg 301 & 502, found 38" pipe in 1" pipe at corner, accessories are besicely same as 1973 LCRC & 2002 1979, Survey, by J. Nelson, Liber 2, Pg 301 & 502, found 38" pipe in 1" pipe at corner, accessories are besicely same as 1973 LCRC & 2002 1983, Survey, by J. Nelson, Liber 2, Pg 301 & 502, found 38" pipe in 1" pipe at corner, accessories are besicely same as 1973 LCRC & 2002 1983, Survey, by J. Nelson, Liber 2, Pg 301 & 502, found 38" pipe in 1" pipe at corner, accessories are besicely same as 1973 LCRC & 2002 1983, Survey, by J. Nelson, Liber 2, Pg 337A, found 1" pipe at corner in centerine and on fence line	5. Private Claims			
NOTE: Not more then 2 corners, ell in the seme town and renge, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration: G-3: Sec. Cor. Common to Secs. 5. 6, 7. & 8, 1727N-186W. Excelsior Township 1852, G.L.O. Resurvey, by George W. Cannon, set post for corner, Sugar 8*, N579E, 10 Lks; 1879, Survey, by D.E. McVean (Co. Surveyor) in Co. Rd. Bk., tied into corner only 1875, Survey, by D.E. McVean (Co. Surveyor) in Co. Rd. Bk., ded at stoner 1873, LCRC, by J.R. Reddiffs, Liber 1, Pg 323, found 1* pipe & edded 3/8* pipe inside 1* pipe, 3* deep at corner in intersection of roads (Hagni & Myen Roads); power pole, \$40*W, 85.56*; 20* Majele, N35*W, 98.34*; t. Pole, \$30*E, 97.12* 1979, Survey, by J. Niston, Liber 2, Pg 501 & 502, found 3/8* pipe in 1* pipe at corner, accessories are besically same as 1973 LCRC above 1983, Survey, by N. Da*vaing, found 5/8* road at corner power piel, \$35*W, 85.56*; 20* Majele, N35*W, 98.36*; 10* Majele, N35*W, 98.56*; 20* Majele, N35*W, 98.56*; 20* Majele, N35*W, 98.56*; 20* Majele, N35*W, 98.56*; 20* Majele, N35*W, 98.30*; 30* Majele, N25*W, 68.90*; power pole, \$35*W, 55.56*; 10* More pipe at corner road sign N35*E, 39.36*; 32* Majele, N26*W, 68.90*; power pole \$41*W, 41.90*; stop slign, N30*W, 58.70* 1891, Survey, by D.R. Farrier, same as 1931 survey above  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-3. Sec. Cor. Common to Secs. 5. 6. 7. 8. 8. T27N.16W. Excelsior Township Found 1/2* fron pipe in more box 1* East of centerline of Hagri Road, in centerline of Myers Road East. Added standard co. Mon. 10 6.L.O. witnesses were found.  C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C-3. Sec. Cor. Common to Secs. 5. 6. 7. 8. 8. T27N.16W. Excelsior Township Found 1/2* fron pipe in more box 1* East of centerline of Hagri Road, in centerline of Myers Road East. Added standard co. Mon. 10 6.L.O. Wit	state that under requirements of f lines 1 and 2 above were in conf current manual of survey instruction Management or by a decree of a C and 5 above were in conformance Decree of a Court of Law; establish	P.A. 74, Michigan P.A. of 19 ormance with regulations and ns of the United States Depart ourt of Law and /or that the c with the rules of the Michiga	70, the corner points mentioned i rules therefore as required in t ment of the Interior, Bureau of La orner points mentioned in lines 3, in Board of Land Surveyors or by	by 5 in 6 18 17 16 15 14 13 18 19 20 21 22 23 24 and 9
A. Description of original monument and accessories and/or subsequent restoration: C-3: Sec. Cor. Common to Secs. 5, 6, 7 & 8, 1727N-R6W. Excelsior Township 1852, G.L.O. Resurvey, by George W. Cennon, set post for corner, Sugar 6*, N57°E, 10 Lkr; Harnlock 20*, S60°W, S8 Lks 1879, Survey, by D.E. McVean (Co. Survey), Co. Rd. Bk., ted into corner only 1895, Survey, by D.E. McVean (Co. Survey), Co. Rd. Bk., ted into corner only 1895, Survey, by L.B. Dinnis (Co. Surveyo), Co. Rd. Bk., Added stone at corner 1873, LCRC, by J.R. Radofffic, Liber 1, Pg 323, found 1* pipe & added 3*Pg ripe in side 1* pipe, 3* deep at corner in intersection of roads (Hagni & Myer Roads); power pole, \$40°W, 56.56*; 20* Maple, N35°W, 68.84*; r. Pole, \$30°E, 97.12* 1979, Survey, by N. DeYoung, found 5*R* rod at corner; power pole, \$35°W, 58.56*; power pole, \$75°W, 77.9*; 30* Maple, N25°W, 68.92*; corner fance post N30°E, 45.7* 1984, LCRC, by B. Jones, Liber 2, Pg 337A, found 1* pipe at corner in centerline and on fence line South, fence post N35°E, 45.88*; 30* Maple, N22°W, 68.95*; power pole, \$35°W, 58.56*; power pole, \$35°W, 58.50*; power pole, \$35°W, 58.50*; power pole, \$35°W, 58.50*; power	NOTE: Not more than 2 comers,	all in the same town and rang	e, may be recorded	
A. Description of original monument and accessories and/or subsequent restoration: C-3: Sec. Cor. Common to Secs. 5. 6. 7 & 8. T27N-R6W. Excelsior Township 1852, G.L.O. Resurvey, by George W. Cannon, set post for corner, Suger 6*, N57°E, 10 Lks; Herrlock 20°, S60°W, 58 Lks 1879, Survey, by D.E. McVann (Co. Survey), Co. Rd. Bk., dided stone at corner 1879, Survey, by D.E. McVann (Co. Surveyo) in Co. Rd. Bk. Added stone at corner 1873, LCRC, by J.R. Raddiffer, Liber 1, Pg 1923, found 1° pipe & added 3/8° pipe in mislé 1° pipe, 3° deep at corner in intersection of roads (Hagni & Myen Roads); power pole, \$40°W, 58.56°; 20° Maple, N35°W, 68.48°; 10° Pole, 580°E, 97.12° 1979, Survey, by J. Nelson, Liber 2, Pg 501 & 502, found 3/8° pipe in 1° pipe a towner, accessories are besically seme as 1973 LCRC above 1983, Survey, by N. DeYoung, found 5/8° rod at corner; power pole, \$35°W, 58.56°; power pole, \$75°W, 77.9°; 30° Maple, N25°W, 68.92°; corner fence post N30°E, 500°F, power pole, \$35°W, 58.56°; NN corner tell. Riser 25°E, 90.05° 1981, Survey, by N. DeYoung, found 1/2° iron pipe at corner; road sign N35°E, 39.35°; 32° Maple, N26°W, 68.90°; power pole \$41°W, 41.80°; stop 1991, N30°W, 58.70° 2000, Survey, by N. DeYoung, found 1/2° iron pipe at corner; road sign N35°E, 39.35°; 32° Maple, N26°W, 68.90°; power pole \$41°W, 41.80°; stop 1991, N30°W, 58.70° 2000, Survey, by N. DeYoung, found 1/2° iron pipe at corner; road sign N35°E, 39.35°; 32° Maple, N26°W, 68.90°; power pole \$41°W, 41.80°; stop 1991, N30°W, 58.70° 2000, Survey, by N. DeYoung, found 1/2° iron pipe at corner; road sign n35°E, 39.35°; 32° Maple, N26°W, 68.90°; power pole \$41°W, 41.80°; stop 1991, N30°W, 58.70° 2000, Survey, by N. DeYoung, found 1/2° iron pipe at corner; road sign n35°E, 39.35°; 32° Maple, N26°W, 68.90°; power pole \$41°W, 41.80°; stop 1991, N30°W, 58.70° 2000, Survey, by N. DeYoung, found 1/2° iron pipe at corner; road sign nature power pole \$41°W, 41.80°; stop 1992, Sec. Cor. Common to Secs. 5. 6. 7 & 8. T27N-R6W. Excelsior Township 1993, Sec	on this certificate.			
C-3: Sec. Cor. Common to Secs. 5. 6. 7 & 8. T27N-R6W. Excelsior Township Found 1/2* fron pipe in mon box 1* East of centerline of Hagni Road, in centerline of Myers Road East. Added standard co. Mon. N42°E, 48.18*, square corner fence post, set nail & tag S15°E, 96.33*, center of phone box, set nail & tag S48°W, 58.52*, power pole, set nail & tag N20°W, 68.82*, 28* Maple, set nail & tag Kelkaska County Peer Group accepted the above monument as the best available evidence of the position of the original corner.  Hattified by Peer Group P.A. 345 - 1990 Kalkaska County Chairman Date	C-3: Sec. Car. Common to Secs. 1852, G.L.O. Resurvey, by George Hemlock 20", S60°W, 58 Lks 1879, Survey, by D.E. McVean (Co. 1895, Survey, by D.E. McVean (Co. 1973, LCRC, by J.R. Reddliffe, Lice Roads); power pole, S40°W, 58.55 1979, Survey, by J. Nelson, Liber 2, 1983, Survey, by N. DeYaung, four fence post N30°E, 45.7' 1984, LCRC, by B. Jones, Liber 2, N22°W, 68.95'; power pole, S35° 1991, Survey, by N. DeYaung, four sign, N30°W, 58.70' 2000, Survey, by D.R. Ferrier, sam B. Description of corner evidence C-3: Sec. Cor. Common to Secs. Found 1/2" iron pips in mon box 1'	8. 5. 6. 7 & 8. T27N-R6W. W. Cannon, set post for corn. Survey), Co. Rd. Bk., tied in Surveyor) in Co. Rd. Bk. Adde rown in Co. Rd. Rd. rown in Co. Rd.	Excelsior Township er, Suger 8", N57°E, 10 Lks; to corner only d stone at corner edded 3/8" pipe inside 1" pipe, 3"; t. Pole, S30°E, 97.12' pipe in 1" pipe at corner, accessopole, S35°W, 58.55'; power pole rner in centerline and on fence lin ser \$25°E, 96.05' ad sign N35°E, 39.35'; 32" Map in restoring or reestablishing corn Excelsior Township	ories are basically same as 1973 LCRC above as, S75°W, 77.9'; 30" Maple, N25°W, 68.92'; corner as South, fence post N35°E, 45.88'; 30" Maple, ble, N26°W, 68.90'; power pole S41°W, 41.90'; stop
P.A. 345 - 1990 Kalkaska County Chairman Date	C-3: Sec. Cor. Common to Sec. Found 1/2" iron pipe in mon box 1' N42°E, 46.18', square corner fenc S15°E, 96.33', center of phone bo S48°W, 58.52', power pole, set n N20°W, 68.82', 28" Maple, set nicology.	s. 5. 6. 7 & 8. T27N-R6W. East of centerline of Hagni R be post, set neil & tag sx, set neil & tag eil & tag eil & tag eil & tag	<u>Excelsior Township</u> oad, in centerline of Myers Road	East, Added standard co. Mon. position of the original corner.
24594 A	Haufied by Peer Group P.A. 345 - 1990 Kalkask	a County		A 63
24594 A	Chairman E	1/2000		FARRIER *
	Date	0		SURVEYOR No. 24594

3026821 Page: 1 of 1 02/16/2001 10:26A REMON LB: 6 PG: 150

FORMA APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1982 REVISED JAN., 1982