

SUHVEY & REMONUMENTATION

ALCOY MANAGES
22.2

MAY 0 9 1996

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIDAN COUNTY OF KEHT RECEIVED FOR RECORD

For corners	in
-------------	----

Property in Sec.

Filing Requirement of Act 74, Mich. P.A. 1970

KENT COUNTY REMONUMENTATION

94 DEC -6 AM 8: 56

REG. OF DEEDS

Kent Located In: Corner Code ## -6N **Public Land Survey** T 5N R 12W 5N **Property Controlling** R in Section Miscellaneous R

7719 Register of Deeds Stamp & File Number

_ , Recorded Plat _ Lot No. Private Claims

Randy Kolehouse June 8 94 , in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United Stales Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1831 G.L.O. Notes 1961 Wit. Map 1975 L.C.R.C. #908 1981 L.C.R.C. #1684 1988 L.C.R.C. #4726 L. Lvon K.C. Surveyor Exxel Engineering

Set Post

1/2" Iron in Mon. Box Williams & Works Fnd. Mon. Box/Set K.C. Mon. Bueche

K.C. Monument

10

11

12

The position of this corner was previously approved by the Kent County Remonumentation Peer Group monumented by Williams & Works on 2/16/81 and was recorded per L.C.R.C. #1684.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Intersection of Division Avenue and 60th Street has been rebuilt and K.C. monument destroyed. Found P.K. nail which checks closely to two remaining witnesses. Decided to reestablish corner using plats and survey records of Williams & Works from 1940's through 1950's and found P.K. to be 0.38' West and 0.25' South of Section Corner location. Reset corner.

L.C.R.C. #1684

NE cor. conc. walks (back of walks) N 50° E 57.60' SW cor. bldg. (brick) N 40° E 97.40' Top C/L Hydt. S 72° W 62.80'

P.A. 345 1990 KENT COUN

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13 Standard Kent County Monument

SW cor. bldg. (brick) N 48° E 96.90' SW cor. brick fndn. N 66° W 82.31'

C/L hyd. N 34° E 76.49'

Nail & K.C. remon. tag in NE side p. pole S 71° E 105.73' P.K. Nail & K.C. remon. tag in NE side t. pole S 60° E 58.64' P.K. Nail & K.C. remon. tag in SE side g. pole N 58° E 58.93' Nail & K.C. remon. tag in SE side p. pole S55° W 62.81'

RANDY J. KOLEHOUSE ENGED LAND SUF

Surveyor's Michigan License No.

25854