SURVEY & REMONUMENTATION

APR 27 1995

4. Lot No. 5. Private Claims ...

expressed below:

STATE OF MICHIGAN COUNTY OF KALAMAZOO

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 95 JRN 13 RM 11 50

For corners in			00 onit 2
Kalamazoo (County)	Located In:	Corner Code ##	م م

T 3 SR 9 W 1. Public Land Survey CLERK - REGISTER ____ R __ 2. Property Controlling 1 pg 1259 S ____ T ___ R __ in Section 3. Miscellaneous S ____ T ____ R ____ Register of Deeds Stamp & File Number Property in Sec.

Gary D. Hahn June 30 , in a field survey on ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

___, Recorded Plat ___

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration: Corner post set by U.S. Deputy Surveyor Robert Clark, Jr. in 1826. Accessories: Lynn 10" S77°E 37 lks. Beech 10" N10°E 45 lks. 1861 F. Stimson accessories: Red Oak 6" N88°W 59½ lks. Swamp Oak 15" N58½°E 73 lks.

1873 Survey by Ed Strong "Stone - evidence slight but exceedingly satisfactory".

1883 F. Hodgeman "Measured from bearing tree of F. Stimson's resurvey and found old stake in place. Set a 3' earthen post even with surface of ground". I.W.M. Inc.: Set capped iron midway between E1/4 cor. sec. 18 and E1/4 cor. sec. 19 and

39.27' (59½ 1ks.) S79°30'E from 42" Oak.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Original corner with accessories not recovered.

Found I.W.M. Inc. capped iron.

Found earthen post (tile) with cap and drill hole 9' below existing asphalt road. Tile is 0.4' west and 5.3' north of I.W.M. Inc. iron. Tile is surrounded by five 4" - 8" stones, broken brick, and ashes.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 12-15-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C7 Corner of sections 17, 18, 19, and 20, T.3S., R.9W.

Found earthen post (tile) with cap and drill hole 9' below existing asphalt road. Tile is surrounded by five 4" - 8" stones, broken brick, and ashes. Tile is assumed to be same as set by F. Hodgeman in 1883 and is accepted as a careful and faithful perpetuation of the original corner position. Placed 30" Harrison monument over tile and set monument box over mon..

Accessories: Fnd. nail in east face of 42" Oak N80°W 36.83'

Fnd. P.K. nail in SEly. face 11" Oak S52°W 45.47' Set P.K. nail in N. face 14" Basswood N55°W 53.43'

NE. Cor. inlet casting S38°W, 44.72'

Signed by 38116 Surveyor's Michigan License No.

LAND SURVEYOR SED LAND SURVIGED FROM 11-4-94

FORM APPROVED BY MICHIGAN STATE BEAUGUET AND SURFICE PROVISE PROVINCE PROVINCE

ANE OF MICA

REVISED JAN., 1983