LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Lake	Located In	Corner Code #			
(County)	Eocatea III	Comer Code #			
1. Public Land Survey	T 18N R 12W				
Property Controlling in Section	S T R				
Miscellaneous Property in Section	S T R S T R R		Register	r of Deeds Stamp &	File Number
4. Lot No:	Recorded Plat:		4 B C D	5 6 6 H 1	1 M t = M
5. Private Claims:			A B C D	E F G H I .	1 K L M
requirements of PA 74, Mir and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	eld survey on March 10, 2014 do her chigan PA of 1970, the corner points imance with regulations and rules the vey instructions of the United States inagement or by a decree of a Court of lines 3, 4 and 5 above were in conformation of Land Surveyors or by a Decree of monumented, recovered, found as ex	mentioned in lines 1 refore as required in Department of the FLaw and/or that the mance with the rules of a Court of Law;	3 4 7 8 5 5 6 18 17 7 7 8 -19 -20 9	9 10 1	1 12 13 -
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 30 29	28272	625
			11	 - - - -	
			12 31 32	33 - 34 - 3	536
A. Description of original	I monument and accessories and/o	or subsequent restoration			
3) NBT – Spruce 7" S15°W 22 L.; 4) NBT – Spruce 5" N18°E 39 L.; 5) NBT – Elm 20" N45°E 58½ L. - 1975 – LCRC L. 2, p. 257 – C. F. Roser (PS #12028) – Recovered Cedar Stake from three Frank Jones witnesses dated 1936, Jones had found stake and one USBT (Tamarack with marks plain) replaced cedar stake with DNR Alum. Capped pipe monument. NOTE: Frank Jones was not a surveyor but worked as a locator for USFS in the 1930's. 6) 9" Cedar N35°W 17.8'; 7) 7" Cedar S15°E 8.0'; 8) 8" Cedar S30°W 27.3'; 9) Cedar Post South 16.5' - 1994 – LCRC L. 3, p. 270 – R. L. Wetherell (PS #24624) – I found DNR Aluminum capped iron in Luther-Baldwin swamp 500'± West of County Road. Condition of the accessories are as follows: 1) Gone; 2) Gone; 6) Gone; 7) Found dead; 8) Found dead; and 9) Found in good condition. I accepted the DNR Monument as a substantial monument for the corner, and is accepted as a careful and faithful perpetuation of the position of the original corner. 10) 8" Cedar N30°W 37.50' (60d spike in NE side of tree); 11) 8" Cedar N35°E 51.48' (60d spike in W. side of tree); 9) 8" Cedar Post (with metal tag) South 16.07' (60d spike in W. side of post); 12) 20" W. Pine N2°E 153.71' (60d spike in W. side of tree) B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: G3 - Section corner common to Sections 3, 4, 9 & 10, T18N, R12W – Fd. 4" Dept. of Conservation (DOC) Aluminum Cap on 1" iron pipe in Cedar swamp. Condition of witnesses as follows: #1 & 2 are gone; #3, 4, and 5 – are gone or the stumps under 2' of snow; #6 7, 8, 9, and 11 are gone or fallen under snow; #10 and 12 are OK. DOC Monument accepted as a careful and faithful perpetuation of the position of the original corner.					
G3 – 4" DOC Aluminum Set Blue Composit N36°W 37.55' to fo N5°W 153.70' to fo S30°W 43.96' to se	f. 60d nail in NE side 9" Cedar (#10d. 60d nail in W. side 22" W. Pine (ent Nail and Tag in NW side 5" W. Fine Nail and Tag in S. side 4" W. Pine Nail and T	0) #12) ² ine	exacting the position $8/12/20$	CR MA	AIG W. ESSIONAL RVEYOR No. 19088
					