LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

	·g ·	4		
For Corners In: Lake	Located in	Corner Code #		
(County)	Located III	Comer Code #		
Public Land Survey	T 19N R 12V	V D6		
Property Controlling in Section	T R			
	S T R			
3. Miscellaneous				
Property in Section	S T R -		Deviates of Deeds	Charma 9 File Namels a
			Register of Deeds	Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G	HIJKLM
5. Private Claims:			2 - 6 - 5 - 4 -	-3
	ield survey on <u>June 18, 2001</u> do		3 7 8 3	10 4 12
requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the				
	, monumented, recovered, found a		8 -19 - 20 - 21 - 21	-2223
NOTE: Not more than 2 corners, all in the same town and range, may				272625
be recorded on this certificate.				
			12 3 3 3 3	35 36
			13	
A. Description of original monument and accessories and/or subsequent restoration:				
D-6 -Frank Jones -1935- CCC survey ran N-S 1/4 line of section 17LCRC- L. 2, P. 8 -G. Blass- 1971. Found iron pipe 16' West of gravel road at curve on the road. Nail & Tag in the SW side of 24" B. Oak N32°W 56.84' Nail & Tag in the SW side of 26" B. Oak S54°E 47.71' Nail & Tag in the East side of 8" J. Pine S08°E 49.21' -Rec. Survey- L. 1, P.163- C. Cole -1971 shows corner -Unrecorded Survey- Ross Surveys #97-1125, 1997. K. L. Ross found Blass monument on West edge of Road and lowered it 1.5'± W. Oak North 59.35' and 3 Blass witnesses noted.				
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:				
D-6 -C ¼, Section 17- Set 2" aluminum cap on 5/8" X 34" rebar at intersection of the 1/4 lines per standard BLM procedure. This position fits the centerline of North-South gravel road extended S'ly, the PC of the road curves SW'ly approximately 100' N. The road was apparently constructed from Jones CCC survey work in 1935, thus I felt the centerline of the road represented the historical North-South 1/4 line and the true intersection of the 1/4 lines the best available evidence of the position of the corner.				
Reference Pt. "B" -S81°49'32"W 32.87' to found 3 1/2" Blass Brass cap on 4" concrete monument in West edge of road curve. A Blass section subdivision map indicated that Blass established this position at the intersection of 1/4 lines but a apparent blunder or error in the subdivision resulted in being incorrectly placed. Cole and Ross have also used this position in their surveys. Using this position would disrupt the historical North-South 1/4 line per Jones and the county road R.O.W. North of the Blass'es monument. In fact parts of the county road just North of Blass'es position would not be in the 66' R.O.W. if centered on Blass'es North-South 1/4 line. Thus Blass monument is not utilized as D-6 in this survey.				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
Set blue carsonite p N43°E 22.50' to set S31°E 31.15' to set S63°W 55.46' to se N36°W 65.48' to se	n 5/8" X 34" rebar- Down 0.5' ost with location tag 10' East nail & tag in SE side of 9" R. I nail & tag in NE side of 7" B. (t nail & tag in NW side of 10" Vt nail & tag in NE side of 11" Vt nail & tag in NE side of 11" Vt to Blass monument -Referen	Maple Dak V. Oak V. Oak	LICENSE	CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by: Surveyor's Michigan I	ice No.: 39088	Date:	11/26/2001	POFESSIONAL
Carragor a miningarit				