

JAN 2 2001

Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Lenawee

(County)

Located in:

Corner Code #



LIBER 1

PAGE 403

STATE OF MICHIGAN  
LENAWEE COUNTY  
FILED

28 JUN 2000 8:42:54 AM

VICTORIA J. DANIELS  
REGISTER OF DEEDS

1. Public Land Survey T-6-S R-3-E B-1  
 T R  
 T R  
 T R

2. Property Controlling S T R  
 in Section S T R

3. Miscellaneous S T R  
 Property in Sec S T R

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Glenn E. Richard in a field survey on May 3, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. This position not established by original government surveyors  
 1973 Werner Sommer set a iron pipe at the intersection of the south line of Section 31, T5S R3E using the monumentation shown on James Blair's 1880± record and by extending the line north from the South 1/4 corner of Section 6 through a R.R. spike found 2.55 South of the south line of Section 31. His notes show "R.R. spike by County" but I can't find any record of how or who set it. He recorded it in Liber 2, Page 453  
 1977 I found iron pipe  
 1986 & 1991 I found iron pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

May 1, 2000 Found 1" iron pipe bent. Straightened it and checked distance S 76° E (648.00') to South 1/4 corner of Section 31, T5S R3E and south line of Section 31  
 May 3, 2000 Replaced the found iron pipe with 30" Harrison Monument stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison Monument stamped P.S. 13040. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

Fd. dbl hd nail & disc in E.P. N 15° E 59.51  
 Fd. dbl hd nail & disc in E.P. N 55° E 41.34  
 Fd. dbl hd nail & disc in E.P. S 20° E 55.52  
 Stop sign post S 65° W 25.45

B-13 T5S R3E S 76° E 648.00

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date May 9, 2000

Signed by Glenn E. Richard Date June 5, 2000  
 Glenn E. Richard

Surveyor's Michigan License No. 13040