

JAN 22 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970



LIBER 1

PAGE 419


For corners in

Lenawee

(County)

Located In:

Corner Code #



1. Public Land Survey T-9-S R-4-E C-2
 T R
 T R
 T R
2. Property Controlling S T R
 in Section S T R
3. Miscellaneous S T R
 Property in Sec S T R

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on September 8, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5				4		3		2		1	
3													
4	7	8				9		10		11		12	
5													
6	18	17				16		15		14		13	
7													
8	19	20				21		22		23		24	
9													
10	30	29				28		27		26		25	
11													
12	31	32				33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1820 Joseph Wampler set 1/4 Sec. post Hickory 6 S 24 E 6 Hickory 8 N 67 E 7
 1914 J.L. Richard surveyed Hodges Hwy. and described the corner as stake and bricks
 1971 Fulton Co. Ohio Engineers found wood stake & set 3/4" gas pipe on top of stake
 1985 I found a iron pipe in the pavement and recorded it in Liber 5, Page 144
 1995 Michael Bartolo found 3/4" iron pipe and recorded it in Liber 5, Page 247

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 18, 2000 The iron pipe was torn out during road construction. Set 5/8" X 3' re-rod by retracing my 1985 survey and a survey by Michael Bartolo done in 1995
 September 8, 2000 Found 5/8" re-rod under base course of new asphalt pavement. Capped with Lenawee County Re-mon cap stamped P.S. 13040 and set monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. iron pipe capped G.E.R. 13040 on 1/4 line West 33.00
 Fd. capped iron M.J.B. 33970 on 1/4 line East 33.00
 Cut "X" on top of catch basin S 25° W 58.42
 Cut "X" on top of catch basin S 20° E 83.00



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date August 22, 2000

Signed by Glenn E. Richard Date Sept. 15, 2000
 Glenn E. Richard

Surveyor's Michigan License No. 13040