

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

Two Corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 45 N. R. 9 E.	H-7
2. PROPERTY CONTROLLING IN SECTION	1. S. R. E.	G-8
3. MISCELLANEOUS PROPERTY IN SECTION	1. S. R. E.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Luckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 2/9 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-7 1/2 Cor. bet. Secs: 15-22, set by William Ives, D.S. 1849.

Bearings were:

Cedar 9" $124^{\circ}E$ 07 lks and Cedar 10" $S42^{\circ}W$ 10 lks.

G-8 1/2 Cor. bet. Secs: 21-22, set by William Ives, D.S. 1849.

Bearings were:

Cedar 14" $S40^{\circ}W$ 27 lks and Cedar 10" $N70^{\circ}E$ 27 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-7 Found no evidence of original corner, or witnesses. Stream crossing to west of corner with record = 5.35 chs. Found some old blazes, both East and West of corner. Placed 1/2 Corner at record distance from stream.

G-8 Replaced 1/2 Cor. from two Cedar stumps in proper position. Stream to North and South checks with record. Also found remains of a cedar at record distance (54.38 chs) for possible line tree. Found a cedar at 1.33 chs. further North of line tree marked in 1854; believe this tree may have been blazed by an inspecting surveyor.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at both corners.

H-7 New Bearings:

9" Cedar $S31^{\circ}E$ 8.7' and 7" Cedar $S55^{\circ}W$ 18.1'

G-8 New Bearings:

6" Cedar $N39^{\circ}E$ 11.7' and 8" Cedar $S77^{\circ}W$ 22.9'

SIGNED BY

Billy D. Luckler

DATE: 3/5/73

SURVEYOR'S MICHIGAN REGISTRATION NO.

8887

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. MLM735
DO NOT WRITE IN THESE SPACES

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 24, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS