

FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Luce County Remonumentation Corner

SECTION

For corners in

Luce County Located in: Corner Code #

1. Public Land Survey T45N R10W F/G-5 (West)
T R
T R
T R #006

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

LUCE COUNTY

REGISTER OF DEEDS

Recorded

Liber 3 Page 959

02-12-2001 09:47:08

Kathy S. Mahar

Kathy S. Mahar, Register

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on October 30, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F/G-5 (West) Meander Corner Common to Sections 9 & 16, T45N, R10W, on the West side of Mud Lake

1849 – Original corner established by William Ives, 8.73 chains (576.18 feet) east of the ¼ corner at F-5.
Witnesses: Tamarack 6, S10°E 26 links – Tamarack 6, N65°W 28 links.

1955 – G.A. Shadko, Survey of Public Fishing Site No. 48-4 at Kak's Lake. Meander corner on the west side of Mud Lake is shown as a found cedar post, 576.4 feet east of the ¼ corner F-5. Witnesses:
Cedar 5, S65°W 26.60' – Hemlock 3, N40°W 12.35' – Hemlock 3, S45°W 14.70'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Luce County Remonumentation Program.
Found a squared cedar post, lying horizontally under the muck on the west side of Mud Lake (also known as Tamarack Lake). Also found another much older 3" x 3" squared, notched cedar post lying horizontally, buried in the muck below the previously described post, possibly the original post as placed by William Ives. The cedar bearing tree from the above mentioned 1955 records is alive and standing. An 8" tamarack is in the approximate position of the bearing tree called out in the 1955 records as a 3" hemlock. The distance west to the ¼ corner at F-5 checks very well with both the original GLO notes and the 1955 records. Placed a ½" x 48" rebar in the hole at the base of the fallen 3" x 3" post.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a ½" x 48" rebar with a stamped aluminum Luce County Remonumentation cap at the corner location, at the base of a found cedar post. Corner falls 40'± from the water's edge of Mud (Tamarack) Lake.

Witnesses:

Nail and plastic witness tag #33142 in blazed (existing blaze) 9" Cedar, S74°W 25.50'

Nail and plastic witness tag #33142 in blazed 8" Tamarack, N40°W 13.00'

Nail and plastic witness tag #33142 in blazed 6" Tamarack, S50°E 28.38'

Nail and plastic witness tag #33142 in blazed Twin 6" Cedar, N74°W 48.68'

Signed by Keith R. Waters

Date 12-29-00

Surveyor's Michigan License No. 33142

