

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 10W T 46N R 11W	A3 same M3 corner
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 07/12/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A3) Section corner common to Sections 6-7 T46N-R10W and Sections 1-12 T46N-R11W. 1841 - Established
by W.A.Burt Deputy Surveyor on the range line 80.00 chains north of Section corner and 80.07 chains
south of Township corner. Set post. Birch 8" N53E 35 links, Hemlock 24" N25W 28 links. 1974 -
Billy D. Buckler RLS reestablished the corner by single proportionate measurement from corners 1 mile
north and 1 mile south. Set 1"IDx36" I.pipe with 4" alum. MDNR cap. 7" S.Maple N71W 33.4', 6"
S.Maple N73E 15.7'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A3) The original post and accessories were not recovered. Found the 1974 monument in good
condition, substantially at the record position between Section and Township corners, and at record
bearing and distance from the 1974 NBTS (the Maple NW in good condition, the Maple NE now dead).
Accepted the monument as a careful and faithful reestablishment of the position of the original
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A3) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Maple N67W 33.1' mrkd "S1" 1974 NBT
4" Maple N44W 2.35' mrkd "S1 NBT"
12" Maple N84E 23.9' "S6 NBT"
6" Balsam S30E 14.35' "S7 NBT"
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 10/26/2010
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources and Environment, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct. 1995