LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 46N R 12W	(GCDB 500500)	
2. Property Controlling in Section	T 46N R 12W S T R S T R	H7 (GCDB 440400)	
3. Miscellaneous Property in Sec.	S T R S T R		
	corded Plat	Register of Deeds Stamp & File Number	
5. Private Claims			A B C D E F G H I J K L
I, Stephan J. Szyszkoski , ir that under requirements of P.A.	n a field survey on 05/ 74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require	3 4 7 8 9 10 11 12	
a Court of Law and /or that the c	7		
re-established, monumented, recove	d of Land Surveyors or by a Decree ered, found as expressed below:	9	
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and range,	may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A Description of original m	Onliment and accompanies and for a	;	13 3 36

- ption of original monument and accessories and/or subsequent restoration:
- (I5) Corner common to Sections 10-11-14-15. 1968 Reestablished by Billy D. Buckler RLS by proportionate measurement between I6 and a line tree north, and at rec. distance east of a Beech line tree. Set 1" pipe with 4" alum. cap. 13" Hard Maple S47°W 26.1'; 14" Beech S67°E 14.6'. 1977 - G.W.Carlson PS, found the 1968 monument and noted these witnesses: 14" Beech N59°E 16.54'; 15" Maple S47°W 26.43'; 14" Beech S67°E 14.95'.
- (H7) Quarter corner common to Sections 15 and 22. In 1980, Billy D. Buckler RLS found and accepted a 3/4" iron set by Mears Engineering and marked new witnesses: 14" dead Cedar S65°E 30.5'; 15" twin Cedar S10°W 67.0'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (I5) Found the 1968 monument in good condition and at record bearing and distance from the 1968 witnesses: The Hard Maple is in good condition, the Beech is dead (both are referenced in 1968 and 1977). The 1977 witness Beech N59°E was not found. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- (H7) Found a 1/2" rebar with nearly illegible plastic cap marked, as best as could be read, "MFT 2???8(?)", by an unknown surveyor (possibly Michael F. Tighe PS27462, judging by the initials and first digit of the license number), at record bearing and distance from the 1980 Buckler witnesses. The dead cedar is still in place, the Cedar S10°W is green and leaning over the river. This monument has been used by other surveyors as control for the subdivision of Sec. 15. Accepted the monument as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Bearings are mag	netic. Coo	ordinates	are	MCS83	in meters	s, NA	D83 (2011)	Epoch	2010.00	datum_
Coord.	Ref.=NGS	PID RJ123	33:	N= 18	3112.192 π	n. E-	8082067.	781 m		1 0
1	n		1						100	4 E U

Surveyor's Michigan License No.

Date

11/10/2015

For the Michigan Department of Natural Resources, Forest Resources Division

YSZKOSK LAND RVFYOR AND SR

TEPHAN J

FORM APPROVED BY MICHIGAN STATE BOARD O