LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	_ Located In:	Corner Code #	
1. Public Land Survey	TR_	11W F3 (GCDB 340600)	
2. Property Controlling in Section	S T R	11W 14 (GCDB 400520)	
3. Miscellaneous Property in Sec.	S T R S T R S T R		
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number 1 A B C D E F G H I J K L N
above were in conformance with r instructions of the United States C a Court of Law and /or that the c	74, Michigan P.A. of 1970, the regulations and rules therefore a Department of the Interior, Burdorner points mentioned in lines of Land Surveyors or by a pered, found as expressed below:	d range, may be recorded	5 6 -18 -17 -16 -15 -14 -13
A Description of original me	anument and a second-		13

- A. Description of original monument and accessories and/or subsequent restoration:
- (F3) Quarter corner common to Sections 4 and 9. 1962 Billy D. Buckler remonumented the corner position from 'two Y. Pine BTs bearing N72°E 09 links and N48°W 35 links; both stumps in fair condition. Corner lies in E-W Fire lane.' 10" Red Pine (1/4S NBT) S53°W 68 links, 14" Red Pine (1/4S NBT) S03°E 60 links.
- (14-Sec. 9) South 1/16 corner between sections 9 and 10. 1977 Established and monumented by Billy D. Buckler 'midway bet. Sec. Cor. South and 1/4 Cor. North. Placed 1" pipe with 4" aluminum cap at corner.' 8" W.Pine, S29°E, 45.0' & 16" W.Pine, N86°W, 65.4'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F3) Found 1962 monument at the surface and on the centerline of an E/W dirt road. This monument was bent badly and was removed. Below the 1962 monument was a 2" pipe in square concrete (typical of Marcus Schaaf, RLS). It is presumed that the 1962 monument was centered over the top the 2" pipe. The 2" pipe is at record bearing and distance from the 1962 witnesses. I accept the position of the 2" pipe as a careful and faithful perpetuation of the position of the original corner, removed it and replaced it with a new monument as described below. No evidence of OBT's.
- (14-Sec. 9) The 1977 position falls in a trail road and the monument was found disturbed and badly bent. Reestablished the 1977 position from the 1977 witnesses, both recovered in good condition with overgrown blazes. This position is 0.4' west and 1.1' south of the 'midway' position described in the 1977 record and is accepted as a careful and faithful determination of the position of the corner. Remonumented the position as described below. From the position monumented, the centerline intersection of dirt trail roads running N-S-E-W is 3 ft. East and 6 ft. North.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

	(F3) Set 1"IDx28" I.pipe with plastic below surface of dirt road. Set measu MDNR tag in the side of: 15" R.Pine N39°E 56.00' mrkd "1/4 7" J.Pine N05°W 15.85' do 19" R.Pine S57°W 45.13' mrkd "1/ 21" R.Pine S02°W 39.88' do E= 8100387.713m N= 209921.741m	g nail with below surface of dirt trail road. Set measuring nail with MDNR tag in the side of: 8" W.Pine S48°W 39.42' mrkd "S1/16 BT" 23" W.Pine N81°W 65.69' do
--	---	--

Bearings are magneti	c. Coord's are MCS83 in me	ters, NAD83	(2011) Epoch 20:	L0.00 dai	-	
Coord. Ref.=	NGS PID RJ0558: N= 209493	3.879m. E= 8	083367.993m.		TE OF MICH	
Signed by Stephen	Impoloali.	Date	01/13/2016		STEPHAN J. SZYSZKOSKI	
Surveyor's Michigan License No.	33986	_			LAND	
For the Michigan Department of Natural Resources, Forest Resources Division, by John Nutkins, PS #52478					SURVEYOR No.	3

FORM APPROVED BY MICHIGAN STATE BOARD OF THE OF RESTO

4 N D Revised by 14, 1975 Sevised Jan., 1983 Revised Oct., 1995