

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

6 Corners.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>42</u> N. <u>6</u> R. <u>6</u> <u>W.</u>	I-6
2. PROPERTY CONTROLLING IN SECTION <u>15</u>	T. <u>42</u> N. <u>6</u> R. <u>6</u> <u>W.</u>	7-Sec.15, 14-Sec.15 6-Sec.15, 9-Sec.15 13-Sec.15
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-21-22, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
 I-6 Quarter Corner bet. Sec's. 14-15, set by H. Brevoort Jr. D.S. in 1845.
 Bearings were: Beech 8", S48°E, 26 lks. and Birch 8", N65°W, 21 lks.
 7-Sec.15 North 1/16 Corner on Eastside of Section 15.
 14-Sec.15 South 1/16 Corner on Eastside of Section 15.
 6-Sec.15 North-East 1/16 Corner of Section 15.
 9-Sec.15 East 1/16 Corner of Section 15.
 13-Sec.15 South-East 1/16 Corner of Section 15.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
 I-6 Corner re-established midway and on line bet. two Sec. Cors. No evidence of original corner.
 7-Sec.15 Corner placed midway bet. Sec. Cor. to North and $\frac{1}{4}$ Cor. to South.
 14-Sec.15 Corner placed midway bet. Sec. Cor. to South and $\frac{1}{4}$ Cor. to North.
 6-Sec.15 Placed corner at center of the NE quarter section.
 9-Sec.15 Placed corner midway bet. Center of Section and the East $\frac{1}{4}$ Corner.
 13-Sec.15 Placed corner at center of the SE quarter section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 Placed 1" pipe with 4" aluminium cap at all corners.
 I-6 New Bearings: 8" Maple, N5°E, 8.8' and 8" Maple, S54°E, 7.6'.
 7-Sec.15 Bearings: 10" Maple, S73°E, 12.8' and 8" Maple, S31°W, 10.1'.
 14-Sec.15 Bearings: 8" Maple, S22°E, 4.8' and 6" Maple, N74°E, 10.2'.
 6-Sec.15 Bearings: 8" Maple, N23°W, 11.7' and 10" Maple, S9°W, 20.1'.
 9-Sec.15 Bearings: 8" Soft Maple, N45°E, 8.8' and 8" Hard Maple, S55°E, 7.2'.
 13-Sec.15 Bearings: 8" Beech, N16°E, 15.1' and 14" Maple, S41°E, 26.2'.

SIGNED BY Billy D. Buckler
 Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
 REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

