LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		rining nequirement of Act 74, Mich.	
	Wackinac (County)	Located In:	Corner Code ≠#
1.	Public Land Survey	T . 42NR7W.	L3
	*.	T R	
		T R	
		T _ , R	
2.	Property Controlling	S11 T42NR7N	7
	in Section	S1 T42NR7W	4
2	Missollaneous	e t p	

Register of Deeds Stamp & File Number

Lot No , Rec	orded Plat _
--------------------------------	--------------

Property in Sec.

September 01, 1993 13 September 01, 1993

1. Staphan J. Szyszkoski , in a field survey on _ ? _ August 25, 1993 _ _ . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- (L3) Quarter corner common to sections 1-12. Corner reestablished in 1965 and recorded in 1972 by Billy D. Buckler as follows: Buried 1 1/4" x 30" iron pipe at corner. New bearings: 9" Beech S40E 60.8", 9" M. Maple S47W 50.3".

(7-Sec. 11) Corner previously monumented and recorded by Gerald Wiggins, RLS, in 1990 as follows: Set DMR monument referenced by 12° Maple NO4E 29.9', 12" Beech N69E 37.7', 8" Beech S55E 15.9', 8" Maple S12E 1.0'. Found no subsequent record.

(4-Sec. 1) Northwest 1/16 corner, Section 1. Corner not established in the original survey. Found no subsequent record.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (13) Found PK nail in asphalt payement at record bearing and distance from the 1965 MBTs. Metal locater indicated presence of iron directly beneath the PK. Remarked the blazes of the 1965 MBTs and marked two new MBTs as described below. Placed measuring nails with tags in all witnesses.

(7-Sec. 11) Found and accepted Wiggins' 1" pipe with 4" aluminum MDNR cap at record bearing and distance from the 1990 NBTs. Placed measuring mails in the NBTs and remeasured as shown below.

(4-Sec.1) Established the corner at the intersection of straight lines connecting opposite 1/16 corners, all monumented. At the position for the corner, I placed a 1"x30" iron pipe capped with a 4" dia. cast aluminum MDMR tablet.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - (L3) Found PK nail

12" Beech \$40E 61.2' with old blazes 11" H. Maple \$47W 50.45' w/ old blazes

14" Beech M30W 55.55' "1/4S NST"

MOOT tag in power pole M60 PC735 N70E

61.3

An & iron spike in a Beech root,

marking a property corner, South 75.00'

[7] Fd. 1° pipe with 4° MDNR cap

12" Maple NO4E 30.4"

12° Beech N69E 38.2'

8" Beach S55E 16.3"

8' Beech \$12E 1.45'

Placed squared 6" Beech post adjacent. N-S trail road is 7' west of the corner. OF 10 / A River E OF MICA

(4) Set 1° pipe with 4° MONA cap. Blazed, scribed and placed measuring

nails in the following bearing trees: 16 R. Pine N20W 11.2' "1/16S BT"

6' R. Pine N20E 19.4' 1/16S BT

10" J. Pine S02W 19.75' "1/16S BT"

10" J. Pine S40W 18.9' "1/16S BT" 12" R. Pine N45W 2.2" "1/16S BT" found an angle iron SOIE 208.87'

∕SZYSZKOSKI

ÆAND SURVEYOR Nο

10-14-93

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971 **REVISED MAY 14, 1975** REVISED JAN , 1983