L. C00004 , P. 00298

9/11/18

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name	Field Survey Date: Dec. 19, 2017											
For corner(s) in:	Midland			County	÷ n		•				 	
Original Public L	Corner Code											
S 2, 3, 10), 11 T	14N R	2W	1-3								
S	T	R	***************************************		٠.,/	ΑВ	CDI	E F	G H	IJ	K L I	M
s	Τ	R			- 1 _[71
S	T	R		- 	2	6	5	44	+3	2	+1	2
Property Controlling Corner				Corner Code	3 4	7-	8	9	10	- 1-1 -	+ - 12 -	3
S	Т	R			. 5		Ţ					5
S	T	R			_	40	4	40	4 "		40	
s	Τ	R		-	- 6	18	- + - 17	- 16 -	- 1 5	- 14	- 13	6
S	T .	R			7	40	20	04	00	100		7
Property Corner				Corner Code	8 9	19	20	21	22	23	24	8
s	Т	R			_ 10	30	29	28	27	26	25	-
S	T	R				30	29	20	21	20	23	
s	T	R			- 11							11
S	T	R			12	- 31	32	- 33 -	- 34	35	36	-
Protracted Public Land Survey Corner				Corner Code	13 ¹ /	A B	C D I	ĒĒ	GH	IJ	K L	⊒ 13 М
S	ТТ	R			_							
S	T	R			_							
S	Т	R			_							
s	T	R			_							

Part A: Corner History

- $\underline{\text{I-3}}$ Corner common to sections 2, 3, 10 & 11, T14N, R2W
 - **1832** GLO J. Wright Set post 1) W. Ash 16" N20°E 19 L.

 - 2) Hemlock 16" S16°W 45 L.
 - 1993 LCRC #754 N. C. Caldwell (PS # 12018) -

[This LCRC is in error being the same description and witnesses as Remon. LCRC #31 for corner 'I-4', T14N, R2W.]

- 1996 MDOT M-20 Road plans; Control Section 'NH56021"; Job Number 36171A & 41155A, Sheet No. 10. Fd. 33mm iron pipe
- 3) S88°E 15.058m 180mm Maple 4) S30°E 6.403m 180mm Maple
- 5) South 9.536m 150mm Maple
- 6) S56°W 14.095m 180mm Twin Maple

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

1-3 - Corner common to Section 2, 3, 10 & 11, T14N, R2W- Found bent up 1" I.D. x 3.5' long iron pipe. Pipe was bent in 'S' like shape. Centerline of E-W 2-track is 17'± North. Dug down 1'± around pipe and find that the last 1.5'± of pipe was still vertical in the ground. No GLO evidence was found. The MDOT witnesses check closely but appear to fit a position on the bent part of the pipe. Felt the vertical portion of the pipe was the best available evidence of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

1-3 - Removed bent 1" x 3.5' long iron pipe and drove 1" x 36" galvanized iron pipe with stamped 4" DNR Aluminum Cap into the vertical hole of the old pipe.

Set Blue Composite Post 1' North

Reset Bent 1" x 3.5' long iron pipe 1' South as guard up 2'.

S30°E 20.81' to fd. 60d nail and brass tag in SW side 10" Red Maple (#4)

S4°E 31.10' to fd. 60d nail and brass tag in W. side 12" Red Maple (#5)
S50°W 46.12' to set nail and tag at fd. nail and tag in NW side Twin 16" & 18" Red Maple (#6)

S89°E 49.51' to set nail and tag at reaction in S. side 17" Red Maple (#3)



Professional Surveyor's License No.:

39088

Prepared By: Craig W. McVean

Michigan Dept. of Natural Resources

8015 Mackinaw Trail Cadillac, Michigan 49601