L. C00004, P. 00299

9/11/18

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean									Field Survey Date: April 24, 2018							
For corner(s) in: Midland Original Public Land Survey Corner							County									
							Corner Code									
S	10, 1	1	T	14N	R	2W	I-4									
s			T		R			/	4 В	CD	E F	GН	IJ	K L	M,	
S			T		R			- 1 _[1						71	
S			T		R	***************************************		2	6-	- + 5	4-	3	2	+1	2	
			•					⁻ 3							3	
Property Controlling Corner						Corner Code	4	· · · 7 -	8	9	- 10 (D-44 -	- 12	4		
S			T		R			- 5			ļ <u>.</u>				5	
S			T		R			- 6	: - 18	47	46	4.5	4.4	40	1	
S			T		R			- 0	סור	17	16	15-	- 14 -	- 13 -	6	
S			T		R			7			ļ		 	+	7	
								8	19	20	21	22	23	24	- 8	
Property Corner							Corner Code	9					<u> </u>	+	9	
s			T .		R			10	- 30	29	28	27	26	25	10	
s		•	T		R			- 11	_,_						11	
S			T		R											
s			T		_R _			12	31	32	- 33	- 34	35 -	- 36		
Protracted Public Land Survey Corner						Corner Code	13	A B	C D I	ĒĒ	GH	l J	K L	վ 13 М		
S			T		R											
S	***************************************		Ţ	··········	R	***************************************		_								
s			Т	*****	R			-								
s		. '	T		R			_								

Part A: Corner History

1-4 -1/4 corner common to Section 10 and 11, T14N, R2W.

1832 - J. Wright - Set ½ section post

- 1) S68°E W. Oak 14" 51 L.
- 2) N57°W 16' Hemlock 19 L.

1938 - J.L. W. - Original cedar post fd. & replaced w/ 1 ½" pipe. Mound of earth around pipe- pipe marked ¼ post.

- 3) SW 32.0' twin 4" oak
- 4) SE 8.3' twin 4" oak blazed

1983 - LCRC #573 - J.L. Jones (PS # 19838) - Fnd 1" pipe as called in 1938

- 5) S2°E 64.67' nail in twin 12" maple
- 4) S45°E 8.40' nail in twin 15" maple
- 3) S45°W 32.06' nail in 16" oak
- 6) N5°W 14.07' nail in twin 5" oak

1993 - LCRC Remon #31 - N.C. Caldwell (PS #12018) - Fnd 23mm (1") iron shaft as apparent replacement for 26mm pipe

- 5) S2°E 19.662m 35cm tw. maple
- 3) S55°E 2.564m 40cm tw. maple
- 4) S50°W 9.750m 40cm W. oak
- 6) N14°W 4.283m 18cm twin B. oak

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

I-4 $-\frac{1}{4}$ corner common to Section 10 and 11, T14N, R2W- Found 1 $\frac{1}{4}$ " O. D. iron pipe with flared top - up 9" - with mound of earth around. Condition of witnesses as follows: #1 & 2 are gone; #3, 4 (maple not oak), 5 & 6 are OK. 1 $\frac{1}{4}$ " iron pipe accepted as a careful and faithful perpetuation of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

I-4 -¼ corner common to Section 10 and 11, T14N, R2W.

Cut off top 2 ½" of said pipe being 5/8" I.D. and 1 ¼" O.D. and Set stamped 2" Aluminum Cap on pipe. Set Blue Composite Post 1' NE.

S45°E 8.33' to fnd. N&T in NE side of twin 18" Red Maple (#3)

N16°W 14.09' to fnd. N&T in NE side of twin 11" and 14" Oak (#6)

S2°E 64.52' to fnd. N&T in west side of twin 16" and 18" Red Maple (#5)

N43°E 41.52' to set N&T in NW side of 6" oak

S52°W 31.89 to set N&T at fnd. nail in SE side 24" W. Oak (#4)



Cario W. Mayora

Date

Professional Surveyor's License No.:

39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail

Cadillac, Michigan 49601