

REMON. COR. I-9, LARKIN TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

518

For corners in
Midland

(County)

Located in:

Corner Code #

1. Public Land Survey

T 15N R 2E I-9

T R

T R

T R

2. Property Controlling
in Section

S T REMONUMENTATION

S T R

3. Miscellaneous
Property in Sec.

S T R FEB 23 2001

S T R

4. Lot No. _____ Recorded Plat _____

SECTION _____

5. Private Claims _____

I, RODNEY CLAYPOOL, in a field survey on May 25, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-9 Corner common to Sections 22, 23, 26 and 27

Survey by Glo, 1830, set post
Survey by F. Gibbs, 1907, 1911, 1918, gas pipe, I-9 to J-9
Survey by Dow Chemical Co., 1951, found
Survey by M. Hunter, 1958, 1960, found
Survey by D. Whittier, 1964, 1968, found
Survey by J. Schafer, 1976, 1983, found
Survey by D. Ankrom, 1976, found 3/8" rebar
Survey by J. Jones, 1981, 1995, found 3/8" rod in monument box
Survey by M. MacDonald, 1984, found
LCRC by J. Schafer, 1977, found 3/8" rod
Larkin Twp. Supervisors Plat No. 1, L-E, P-46
Woodland Est. No. 1, L-I, P-3, 4, 5 & 6

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-9 Corner common to Sections 22, 23, 26 and 27

Found 3/8" rod in monument box per surveys by F. Gibbs, Dow Chemical Co., M. Hunter, J. Schafer, D. Ankrom, J. Jones, M. MacDonald and LCRC by J. Schafer, and fits existing plats.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9 Corner common to Sections 22, 23, 26 and 27

Replaced rod with 3/4" pipe and brass cap stamped Midland Co. Remon Cor PS 29241, and is accepted as the best available evidence of the position of the original corner.

S 45 Deg E, 63.80, nail and tag in power pole, Rec. 63.79
S 20 Deg E, 88.24, nail and plastic disc in power pole, Rec. 88.08
S 30 Deg W, 45.11, nail and plastic disc in light pole
N 70 Deg W, 75.77, nail and plastic disc in 10" Maple
N 45 Deg E, 43.83, centerline water valve
South, 2.8', centerline Monroe Road

Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12.12.00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

12/27/00 JFG