## Land Corner Recordation Certificate Authority: 1970 PA 74, MCL 54.205

Surveyor's Name:	Craig W. M	cVean			Field	Surve	y Date:	June	14, 201	7		
For corner(s) in:	Midland			County								
Original Public La	Corner Code	Corner Code										
S 29&3	32 T	16N R	01W	D11								
S	Т	R			Α	В	DD	EF(	ЭH	IJ	K L M	Μ.
S	Т	R			ີ <sup>1</sup> [	1					:	٦ <u>1</u>
S	Т	R			- 2	- 6	- 5	4	3	- 2		2
10 m					3	i				- ā -		3
Property Controlling Corner				Corner Code	4		- 8		- 10 -	- 11 -	12	-4
S	T	R			- 5	1		T				5
S	Т	R		728		40	47	10	4.5			1
S	Т	R			- 6-	18	17	1 <del>6</del>	- 15 -	- 14	-13	6
S	Т	R			- 7	<u>-</u>			+		- !	7
					8	19	20	21	22	23	24	8
Property Corner			Corner Code	9	÷		i	i.		1	- 9	
S	Т	R			10	30	29	28	27	26	25	10
S	Т	R			- 11 -							
S	Т	R			- I						i	11
S	Т	R			-12-	-31	- 32 -	- 33	- 34	- 35 -	- 36	12
Protracted Public Land Survey Corner			Corner Code	-13 ∟ ∕	BO	DI	EF (	GΗ	IJ	< L M	J13 M	
S	Т	R										
S	T	R			_							
S	T	R			_							
S	T	R		· · · · · ·	-							

## Part A: Corner History

D11 – ¼ corner common to Sections 29 & 32, T16N,R1W

**1832** - GLO – H. Parke – Set ¼ post 1) Pine 24" S67°E 16 L. 2) Maple 10" S70°W 4 L

- 1852 - GLO Dependent Resurvey - A. Burt – Old ¼ corner. Set post
3) W. Pine 24" S42°W 27 L.
4) W. Pine 18" N31°E 31 L.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

D11 – ¼ Corner common to Sections 29 & 32, T16N, R1W– No conclusive GLO BT's or post was found. Only one pine stump was found in the area but could not make it fit a reasonable position. Corner was reestablished based on the following retracement: From corner 'C11' –original GLO corner- measured grid bearing and distance of S89°30'41"E 2050.30' [S89°51'E 31.18 Ch. (2057.88') W. Pine 20 in diam –GLO] to set 2" aluminum cap on 5/8" x 34" long rebar in CL. remains of 20" +/- White Pine Stump (WPS). Continuing S89°30'41"E 563.74' [8.56 Ch. (564.96') old qr. post. Set post-GLO] to set DNR monument for ¼ corner by proportion between line trees E & W on extension of section line east from 'C11' through line tree to west. Thence S89°21'35"E 1313.87 [S89°43'E 19.95 Ch. (1316.7') W. Pine 18 in diam –GLO] to set 2" Aluminum Cap on 5/8" x 34" long iron rebar in CL. remains 18" +/- WPS. The ¼ corner falls on south edge of small E-W drain. Measured east 268' [4.06 Ch. (268') drain an swale C. SE- GLO] to west side of stream swale. CL. of 2-track ENE-SW is 60' south. DNR monument accepted as a careful and faithful reestablishment of the position of the original corner.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

D11 – ¼ Corner common to Section 29 & 32, T16N, R1W. Stamped 4" DNR aluminum cap on 1" x 3' long galvanized iron pipe. Set blue composite post 1' N. S07°E 19.64' set N & T in SE side 10" Oak scribed 'XBT' S52°E 13.65' set N & T in SW side 6" W. Oak N42°E 34.70' set N & T in NW side 4" Oak N20°W 14.78' set N & t in NE side 5" Oak



9/5/2017

Craig W. McVean

Professional Surveyor's License No.: 39088

Prepared By: Craig W. McVean Michigan Dept. of Natural Resources 8015 Mackinaw Trail Cadillac, Michigan 49601