

APPROVED LAND CORNER

P.A. 345 OF 1990
MIDLAND COUNTY

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970
Midland County Remonumentation

501

9/24/00For Corners in
Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 16N R. 2W L-13T. R. T. R. 2. Public Controlling
in SectionS. T. R.

3. Miscellaneous

S. T. R.

Property in Section

S. T. R. 4. Lot No. , Recorded Plat 5. Private Claims SECTIONSTATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 15, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1830, Clark
Pine 12" N28°W, 7 LINKS
Maple 6" N23°E, 27 LINKS

1909, Gibbs, CSR
Set pickett with plow point at
average distance on line
Pine stump N49°W, 52 ½
Pine stump S63°E, 72 ½
Meas. 40.00 both ways

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Established S.P.M. position and searched for corner. Found 5/8" rerod on C.L. of 10 feet deep County Drain to North and on North edge of Asphalt and 5 feet South of Meas. section line and 4 1/2" West of S.P.M. position. Concluded that 5/8" rerod was in wrong position and accepted S.P.M. position as best available evidence of the original corner position. Measured East and West 2637.32 feet to Section Corners. S39-59-30W, 6.84' - 5/8" re-rod on C.L. 10' deep drain North (Removed re-rod).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 18" pipe w/brass cap stamped with "Midland County Remon P.S. #27458" in Mon. Box.

Witnesses:

South, 14.7' - C.L. Asphalt Pvm't
West, 16.64' - L-1, T15N, R2W
S74°E, 191.54' - N & T in Cen. Cut-off T.P.
N15°W, 76.30' - N & T in P.P.

Signed by Mark R. RobisonDate 9-15-2000Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1977

REVISED MAY 14, 1977
REVISED JAN., 1978