REMON CORNER M-6, WARREN TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

K L

12

13

24

25

36

STATE OF MICHIGAN MIDLAND COUNTY REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES REGISTER OF DEEDS

3

10

15 14

22

27

34 35

11

23

26

Register of Deeds Stamp & File Number

D

5

8

17

20

29

32

6

7

18

19

30

5

7

10

11 31

12

13

E F G н 1 J

9

16

21

28

33

For comers in Midland (County) Located in: Corner Code # 1. Public Land Survey T <u>16N</u> R <u>2W</u> R SURVEY & REMONUMENTATION 2. Property Controlling S in Section 3. Miscellaneous R Property in Sec. SECTION

, Recorded Plat 5. Private Claims

I, RODNEY CLAYPOOL, in a field survey on June 11, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, menumented reconstructions of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, menumented reconstructions of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1/4 Corner for Section 13 on East townline M-6

Survey by Glo, 1830's, set post Survey by F. Gibbs, 1904, old corner post standing Survey by MDOT, 1937, did not find LCRC by D. Ledy, 1988, set RR spike

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-6 1/2 Corner for Section 13 on East townline

Found RR spike at position per LCRC by D. Ledy.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
- M-6 1/4 Corner for Section 13 on East townline

Replaced RR spike with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 in monument box and is accepted as th best available evidence of the position of the accepted corner.

N 74 Deg W, 41.10', chiseled "+" in concrete pipe N 48 Deg W, 53.07', chiseled "+" in concrete pipe S 54 Deg E, 65.23', nail in 6" Ash S 89 Deg E, 57.18', nail in fence post (Rec.) South 8.25', Edenville Twp. corner A-5 East 4.8', centerline M-18 (Rec.)

Signed by . Surveyor's Michigan License No.

12-26-00 Date

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

P.A. 345 OF 1990

12/27/00

APPROVED LAND CORNER MIDLAND COUNTY