LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	_ Located In:	Corner Code #						
1. Public Land Survey	T 47N R 29W T 7 47N R 29W	C8 (GCDB 200340)						
2. Property Controlling in Section	S T R S T R	(GCDB 300340)						
3. Miscellaneous Property in Sec.	S T R S T R		Peg	ictor of C	Deeds Sta	9 Eil	m Normala a	
4. Lot No. Red 5. Private Claims	corded Plat		1 A B	C D		G H		K L M
	C8 06	/10/15	2 6-	 	┷┼─-∳-	┿-		 - ¦
above were in conformance with	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require	ed in the current manual of survey	5	8-	9-	10-	11-	-12-
a Court of Law and for that the c	Department of the Interior, Bureau of La corner points mentioned in lines 3, 4 and	and Management or by a decree of	6 18-	17	16	15-	1-14-	13-
the rules of the Michigan Board	d of Land Surveyors or by a Decree	of a Court of Law; established.	8 19	20	,	1 32	1,	
re-established, monumented, recover		,	9					
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and range	, may be recorded	10 30-	29	28-	27_	26-	25_
			13					36

A. Description of original monument and accessories and/or subsequent restoration:

(C8) Quarter corner common to Sections 19 and 20. 1848 - Established by John Burt, Deputy Surveyor, midway and on line between Section corners 40.00 chains north and south. Set post. Spruce 12" S74°W 25 links, Spruce 12" N40°E 33 links. Found no subsequent record.

(E8) Quarter corner common to Sections 20 and 21. 1848 - Established by John Burt, Deputy Surveyor, midway an on line between Section corners 40.00 chains north and south. Set sugar qr. Section post. Spruce 16" N80°E 12 links, Sugar 20" N50°W 20 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C8) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2645.98' north and south.

(E8) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2611.51' north and south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set measuring hall with MDNR tag in the side of: 4" W.Birch S20°E 20.9' mrkd "1/4S NBT" 2" Poplar S23°W 17.7' "X X" 2" Poplar N71°W 18.3' do 2" Poplar N07°W 3.5' do Set cedar post adjacent.	(E8) Set 1"IDx28" I.pipe with 2" Set measuring nail with MDNR tag 13" W.Pine N60°E 12.7' 8" W.Pine S13°E 17.3' 13" W.Pine S44°W 19.2' 15" W.Pine N18°W 15.9' Set cedar post adjacent. E= 7927051.980 N= 186404.280	in the side of: mrkd "1/4S NBT" do do do
--	--	--

Bearings are magnetic.	Coordinates are	MCS83 in meters,	NAD83 (2011)	Epoch 2010.00	datum

Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

33986

Signed by Stephen markel, Date 06/23/2015

For the Michigan Department of Natural Resources, Forest Resources Division

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROTESTIONAN 3 SERVICES AND PROTESTION OF THE STATE OF

Avvised Oct., 1995

OF MIC

YSZKOSK

STEPHAN .

LAND