LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #	!
1. Public Land Survey	T 48N R 30W	G6 (400440)	
2. Property Controlling in Section	T 48N R 30W S T R S T R	(300440)	
3. Miscellaneous Property in Sec.	S T R S T R		ts.
4. Lot No. Rec	corded Plat	Į	Register of Deeds Stamp & File Number
5. Private Claims			A B C D E F G H I J K L
above were in conformance with i	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require	ed in the current manual of supress	,5
a Court of law and for that the	Department of the Interior, Bureau of La	6 -18-17-4-16-4-15-14-13-	
the rules of the Michigan Board	forner points mentioned in lines 3, 4 and	7	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			9
NOTE: Not more than 2 corp	ers all in the same town and war	1	10 -30 -29 -28 -27 -26 -25
on this certificate.	ers, all in the same town and range,	may be recorded	11
on this certificate.		1	12 31 32 33 36 35
	S	1	13
A. Description of original mo	onument and accessories and/or s	ubsequent restoration:	
(G6) Quarter corner comidway and on the second	Ommon to Sections 15 and 1	16. 1848 - Established corners 40.00 chains	ed by Wells Burt, Deputy Surveyor north and south. Set cedar

(E6) Quarter corner common to Sections 16 and 17. 1848 - Established by Wells Burt, Deputy Surveyor midway and on the section line between Section corners 40.00 chains north and south. Set cedar post. Fir 12" N46°W 18 links, Fir 6" S80°E 22 links. Found no subsequent record.

post. Maple 7" S32°E 16 links, Maple 10" N9°W 16 links. Found no subsequent record.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (G6) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2631.96' north and south.
- (E6) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2621.60' north and south.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set measuring nail with MDNR tag in the side of: 3" Sugar S47°E 28.4' mrkd "1/4S NBT" 3" Hemlock S36°W 21.0' do 4" Maple S27°W 12.1' do 4" Maple S77°W 10.4' do 4" Maple S06°W 8.25' do 3" Hemlock N50°W 25.9' do 8" W.Birch N70°W 1.05' do Set sq'd cedar post adjacent.		
	3" Hemlock S36°W 21.0' do 4" Maple S77°W 10.4' do	Set measuring nail with MDNR tag in the side of: 9" W.Birch S65°E 1.15' mrkd "1/14S NBT" 4" Maple S27°W 12.1' do 4" Maple S06°W 8.25' do 8" W.Birch N70°W 1.05' do Set sq'd cedar post adjacent.

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.	E OF MICH	
	STEPHAN J. SZYSZKOSKI	
Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Resources Division	SURVEYOR	*

FORM APPROVED BY MICHIGAN STATE BOARD O .av 14, 1975