LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #	
1. Public Land Survey	T 48N R 30W	C5 (GCDB 200500)	70
2. Property Controlling in Section	T 48N R 30W S T R	F7 (GCDB 340400)	
3. Miscellaneous Property in Sec.	S T R S T R R		,#1
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number 1 A B C D E F G H I J K L M
I, Stephan J. Szyszkoski, in a field survey on 06/10/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corn on this certificate.	ners, all in the same town and range,	, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (C5) Section corner common to 7-8-17-18. -1848 Established by Wells Burt, Deputy Surveyor. post. Y.Birch 20" N55°W 38 links, Spruce 6" S40°E 24 links. Circa 1935 to 1945 - County Road Commission notes in Field Book #656, presumed made by surveyor J. Heilala state "Post in swamp. B.T. Spruce 6 S40°E 14 in good condition". Found no subsequent record.
- (F7) Quarter corner common to Sections 16 and 21. 1848 Established by Wells Burt, Deputy Surveyor midway and on the Section line between Section corners 40.00 chains east and west. Hemlock 18" for Fir 6" N29°W 10 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (C5) The original post and accessories were not recovered. Found a rotting wood post with Mead Corp. location poster facing it. The post is about 15 ft. southeast from the calculated double proportionate position for this corner. Accepted the post as the best available evidence of the position of the original corner and replaced it with a monument as described below.
- (F7) The original corner tree and accessory were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2629.82' east and west.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C5) Set 1"IDx32" I.pipe with 2" alum. MDNR cap. (F7) Set 1"IDx32" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 6" B.Spruce N82°E 19.8' mrkd "S8 NBT" 5" Maple N28°E 7.45 mrkd "1/4S NBT" 7" B.Spruce S42°W 3.8' "\$18 NBT" 7" Maple S14°W 25.9' 7" B.Spruce N56°W 10.05' do "S7 NBT" 7" Sugar N89°W 10.6' do 7" B.Spruce N21°W 8.6' "S7 NBT" 6" Maple N40°W 10.35' do Set sq'd spruce post adjacent. Set sq'd cedar post adjacent. E= 7915957.467 N= 198485.363 E= 7918345.902 N= 196863.426

> Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Surveyor's Michigan License No.

Signed by

33986

For the Michigan Department of Natural Resources, Forest Resources Division

Date

LAND

SURVEYOR No

STEPHAN J

SZYSZKOSKI