

1993

Filing Requirement of Act 74, Mich. P.A. 1970

P.A. OF 1990 On 12/28 19923

Located In:

Corner Code #

- | | | | |
|------------------------------------|---------|---------|---------|
| 1. Public Land Survey | | T 32N | R 27W |
| | | T _____ | R _____ |
| | | T _____ | R _____ |
| | | T _____ | R _____ |
| 2. Property Controlling in Section | S _____ | T _____ | R _____ |
| | S _____ | T _____ | R _____ |
| 3. Miscellaneous Property in Sec. | S _____ | T _____ | R _____ |
| | S _____ | T _____ | R _____ |

J-7

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, WILLIAM LENCA, in a field survey on Sept. 17 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:**

ORIGINAL B.T.'s: Cedar, 10", N59°W, 12 lks
Birch, 8", S16°E, 07 lks

Original Survey by James H. Mullett in 1848. All original evidence for this corner has been destroyed by county road improvements.

PERPETUATION: Robert Olsen, RLS No. 10700, shows this corner in surveys dated May 17, 1958; June 20, 1961; and Sept. 23, 1965.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

In a June 1981 Survey, I located a 1/2 inch diameter Iron Rod in the centerline of a County Road East-West and in line with an old fence running North from this location, as indicated by Robert Olsen's Surveys noted above. In August of 1984, I replaced this Iron with a Fiberglass Berntsen Monument 30 inches long/4 inch aluminum cap. On Sept. 17, 1993, we found this monument in place with the top sheared off by a snowplow. This corner fits well with existing occupation, has been used by local surveyors over the past 30 years, and is accepted as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner in Monument Box:

Set 5/8" x 24" Iron Rod/2" Alum. cap marked WITNESS MARKER	N59°E	50.84 feet
Set 5/8" x 24" Iron Rod/2" Alum. cap marked WITNESS MARKER	N10°W	29.76 feet
Northwest Corner of House Foundation	S26°E	111.42 feet
Northeast Corner of House Foundation	S29°W	121.17 feet
Metal Survey Sign Post	N10°E	33.0 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape.
All distances to trees are measured to nails in side of tree.

Signed by _____ Date December 27, 1993

Surveyor's Michigan License No. 26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

[illegible]