1993

LAND CORNER RECORDATION CERTIFICATE

COMMISSION Filing Requirement of Act 74, Mich. P./

1970			MO IN C					
			,	[]] _[-]	JA 174	eli		
			Z.,)	>				
			里面	ger ?		3		
			350	n ₌₁ ; >		⊋ `		
			Z	2,c	63 6	<u> </u>	•	
			m-o	~ ~	ည့ <i>်</i>	7	į	
			- 도위 _전	3.6		7 2 3	:	
				0 K	2	. CE	•	
			498	<u> </u>		3		
			25.00	9 '	လု၊ လု၊ ် လု	Š		
			W . 3	Z	Ċ,	-		
Rea	iste	er of D	eeds S	Stamp	& File	Numbe	er	
		-						
		АВ	C D	E F	Э H :	ЭК	L M	
	1	-	1					
	2	ļģ	5	4	-3-	2		
	3		<u> </u>					
	4	}	a	φ	10	17	12	
		1	8	Y	i.u	11	12	
	5		- קו					
	ó	18	17	16	- 15	14	- 13	
	7]	1			
	8	19	- 20-	21	22	23	24	
	9	LÏ		. ~ii .		1		
				1				
	10	30	- 29	-28	27	26	-25	
	11	┡┷┿╾		 - 				
	12	-31	- 32	- 33	-34-	-35	-36	
	13		<u>. I</u>		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
	1.0							
		a.						

For corners in

MENOMINEE

Located In:

Corner Code #

1. Public Land Survey

2. Property Controlling

Miscellaneous Property in Sec. 32N R 27W R R R

R R

Recorded Plat

4. Lot No. 5. Private Claims

in Section

WILLIAM LENCA , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentione in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: Tamarack, 18", N30°E, 14 lks Cedar, 6", N45°W 10 lks ORIGINAL B.T.'s: 10 lks

Original Survey by James H. Mullett in 1848.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I had set a 1/2 inch diameter Iron Rod, 18 inches long in a August, 1981 survey. The Iron has been destroyed, but the corner position was re-established from 4 bearing trees which I had marked in 1981. The corner was set in line with the centerline of a county road and lane running East from this position. The East-West position for this corner was established by doubling the distance from the Northeast Corner (C-1) and the East 1/16 fence. This position checked with a GLO Terrain call to a well defined 14 foot high ridge 264 feet West. This corner is accepted as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Berntsen Drivable F-130 Aluminum Monument stamped for corner: AL OF MICHIE

6 11	dia.	Spruce	n48°e	17.17 feet
5"	dia.	Tamarack	520°€	24.30 feet
6ª	dia.	Cedar	850°W	25.08 feet
бπ	dia.	White Birch	N43 ⁰ W	11.33 feet
Me	tal S	urvey Sign Post	North	0.75 feet

All bearings are magnetic bearings. All distances are measured to nails in side of tree. All distances are measured with steel tape.

Ce) llian Signed by

December 27, 1993

Surveyor's Michigan License No. 26461

Date

(ATE ROARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

WILLIAM LENCA' SURVEYOR