

SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 10/31 1992
Michael RLS
Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
SECTION
MENOMINEE
(County)

Located In: Corner Code #

- | | | |
|------------------------------------|------------------------|---------------|
| 1. Public Land Survey | <u>T6N</u> <u>R24W</u> | <u>F/G-03</u> |
| | T R | (003) |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William Lenca, in a field survey on Aug. 27, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3							9						
4	7		8			9		10		11		12	
5													
6	10		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

- A. Description of original monument and accessories and/or subsequent restoration:
1848: Original Survey by James H. Mullett - B.T.'s - Aspen, 10" - N40°W - 103 lks.; W. Pine, 10" - S86°W - 118 lks. All original evidence for this corner has been destroyed by shore line erosion.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1 inch diameter iron pipe at the shore of Green Bay and on line with an ancient fence line running West, and lying 1.6 feet South of a straight line extension between the Northwest Corner and the North Quarter Corner of Section 9. The GLO distance from the N1/4 Corner of Section 9 to the shore of Green Bay was recorded as 2022.9 feet. Our measured distance to the found iron pipe at the shore of Green Bay is 1916.4 feet. We re-established the Meander Corner on line between the North Quarter Corner of Section 9 and the existing iron pipe on the shore of Green Bay at a distance back from the shore where it would not be destroyed by shore erosion. We accepted this location as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Sct 3/4" dia. x 4' long aluminum rod 3-1/4" dia. Alum. cap stamped for corner:

S.E. Corner of Residence	N16°E	52.16 feet	
8" dia. White Pine	S40°E	9.09 feet	Scr. NBT
5" dia. White Ash	N88°W	26.17 feet	Scr. NBT
1" Iron Pipe	East	42.65 feet	
Metal Survey Sign Post			

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Sep. 05, 1997

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date _____