

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

15528pc778

LAND CORNER REGORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		\$ 7.00 RISCELLANEOUS RECORDING \$ 2.00 REMONDMENTATION	
Oakland Located In	n: Corner Code #	19 JUL 95 2:04 P.M. RECEIPT# 716	
(county)		PAID RECORDED - OAKLAND COUNT LYNN D. ALLEN, CLERK/REGISTER OF DEED	
1. Public Land Survey T1N R8	E K-8	Compliance with	,,,
TR		ACT 345, P.A. 1990	
ı r		APPROVED ON: 7-12-95 Tou-S OAKLAND COUNTY REMONUMENTATION	
2. Property Controlling S T R		PEER GROUP COMMITTEE	
in Section ST_R		1	
T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R		Register of Deeds Stamp & File Number	
			_
4. Lot No, Recorded Plat		ABCDEFGHIJK	L
E Drivete Oleven			Ţ
5. Private Claims			
I, Joseph C. Kapelczak in a fie	d survey on February 10 , 1995		Ţ
do hereby certify that under requirements of P mentioned in lines I and 2 above were in conformant	.A. 74, Michigan P.A. of 1970, the co ice with regulations and rules therefore	orner points as required 5	Ï
in the current manual of survey instructions of the	e United Slates Department of the Inter	ior Bureau e	.
of Land Management or by a decree of a Court lines 3, 4 and 5 above were in conformance with t			+
or by a Decree of a Court of Law, established			-24
recovered, found as expressed below:		9	╁
NOTE: Not more than 4 corners, all	in the same town and range,	may be 10 30 29 28 27 26	- <u>4</u> -
recorded on this certificate.	•	╵ ╏ ┤ ┤ ┤ ┤ ┤ ┤	†
A. Description of original monument and ad	cessories and/or subsequent resto	pration: 12 31 32 33 34 35	-36 1
Post set in 1816 G.O.L. survey: N 34 E 12II	ks 14" Sugar: N 56 W 10lks 18" i		-
·		5000ii.	
LCRC L6212 P 262 Stonerock 1973	LCRC L 7716 P211 Anderson 1980		
Found 1" pipe	Found 1" pipe		
West 57.77 Nail in power pole	West 57.77' Nail in power pole	à'	
S 45 E 43.90' Nail in 24" Oak	S 45 E 43.90' Nail in 24" Oak		
B. Description of corner evidence found an	d/or method applied in restoring or	reestablishing comer:	
Recovered 1/2" rerod in remonument box of	n centerline Meadowbrook Rd		
Recovered witnesses: S 21 W 129 .45' Punch mark north flange	holt on hydrant		
\$ 67 W 45.61' Nail southeast side power			
N 87 W 57.98' PK tag #24598 north side			0
N 87 W 57.87' Nail w/OCRC tag north sid S 76 E 46.91' Nail tag #24598 north side 1		•	6
🖐 S 75 E 47.81' Nail w/MDSH tag south side	e 18" Walnut		
¥ S 75 E 46.95' Nail w/OCRC tag south side ¥ S 42 W 100.57' Monument northeast corr	• 18" Wainut per parcel #22-23-426-013		
C. Description of monument for corner and	accessories established to perpet	uate locating the position of the corner:	
Set 5/8" rerod with O.C. Remonumentation	hroce can raplacing 10° rared	E OF MICHI	
Octor follow wan old. Nemonumentation	biass cap replacing the reloc.	65	
S 21 W 130.01' Tip of arrow on fire hydra		JOSEPH C. No N	
N 67 W 45.76' PK/remon tag southeast si N 87 W 57.70.' PK/remon tag north side p		PROFESSIONAL	
S 76 E 46.80' PK/remon tag north side 18		SURVEYOR No.	
		24598	
.l .	0	POPULATION	
A = A A A A A	//	TESSIO!	
Signed by Jacob Chapelers	Date 6	128/95	
Surveyor's Michigan License No.	ILEGR	POWED BY MICHEAN STATE POARD OF AND CHIEF COME IN CO.	74
OWITE OF STREET IN LICEUSE INC.	FORM APPR	OVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197	