For corners in LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	
Oakland Located In: Corner (West Bloomfield Township 1. Public Lang Gurvey TZN R9E D- T R T R T R T R T R	\$ 7.00 MISCELLANEOUS RECORDING \$ 2.00 REMONUMENTATION 30 NOV 98 8:37 A.M. RECEIPTH 25A PAID RECORDED - CAKLAND COUNTY G. WILLIAM CALDELL CLERK/REGISTER OF DEEDS
in Section 3. Miscellaneous STR Property in Sec. STR	Compliance with ACT 345, P.A. 1990
4. Lot No, Recorded PlatSECTION	APPROVED ON: 9-16-92 JS OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE Register of Deede Stamp & File Number
I. Huston K. Kennedy , in a field survey on August 5 , 1998 do requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lin conformance with regulations and rules therefore as required in the current manual the United States Department of the Interior, Bureau of Land Management or by a and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformal Michigan Board of Land Surveyors or by a Decree of a Court of Law; est monumented, recovered, found as expressed below:	I and 2 above were in 2 5 5 5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
NOTE: Not more than 2 corners, all in the same town and range, may be on this certificate.	8 29 20 21 22 23 24 9 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
A. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Carpenter, D.S.; Post was not set, corner falls in a lake 1.) 1987-DeKeyser, PS #30080; LCRC L.9897, Pg.542 – Set a "T" Iron 2.) 1992-Scharl, PS #19843; LCRC L.12333, Pg.53 – Fnd a Fence Post 3.) Giffels-Webster Engineers, Inc., Survey L.12908, Pg.119 – Object found not stated, no witnesses 4.) Giffels-Webster Engineers, Inc., Survey L.12908, Pg.120 – Object found not stated, no witnesses 5.) 1998-JCK & Associates, Inc. Unrecorded Witnesses – Fnd a "T" Iron.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998-Kennedy Surveying, Inc. – Kennedy, PS #17623 - Fnd a "T" iron that is 21 feet East of the water's edge of Pleasant Lake. The corner as found does not agree with the existing monumentation as found in "PLEASANT LAKE HIGHLANDS".	
Witnesses from LCRC #1 & 5 were used to recover and verify the location of the found "T" Iron.	
I accepted the found "T" Iron as the best evidence of the original	fy the location of the found "T" Iron. John John John John John John John John
FIELD MEASURMENTS BETWEEN	2,3)
<u>D-9 to C-9</u> No GLO, corner falls in a lake "PLESANT LAKE HIGHLANDS" (Sec 29) = 2643.70 Ft. 2643.70 Ft. Survey 2646.54 Ft. (GPS-MEA)	D-9 to E-9 No GLO, corner falls in a lake "PLEASANT LAKE HIGHLANDS" + Parcels (Security)" 2648.91 Ft. (GPS-MEA) HISTON
C. Description of monument for corner and accessories established to perpetuate locating the position of the differ D-9 I replaced the found "T" Iron with a 4" diameter Concrete Monument with a ½" Iron Rod 36" light with a 2" glant expension of the differ stamped Oakland County Remonumentation PS #17623 Due North 7.03' Set Mag Nail & Remon Washer East face 12" Maple S63°E 10.34' Set Mag Nail & Remon Washer NE face 12" Elm S12°W 84.95' Set Mag Nail & Remon Washer East face 31" Poplar S51°E 167.87' Set Mag Nail & Remon Washer NE face 37" Ash West 9.00 feet found ½" Iron Rod @ fence corner set in concrete	
The selected location is accepted by me and is generally accept the position of the priginal comer.	
Surveyor's Michignan License No. 17623	Date /0-9-98