## COPY

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Oakland	- · · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·	
(County) Located In: Corner Code #	•
vvest Bloomfield Township	\$ 7.00 WYOSHI LAND
1. Public Land Survey	\$ 7.00 HISCELLANEOUS RECORDING
T2N R9E G-5	23 THE GO LAND THE HILL TON
R OF THE PROPERTY OF THE PROPE	PAIU REPROPER RECEIPTH ?
IR	LYNN D. ALLEN. CLEDED - OAKLAND COU
2. Property Controlling	LYAN D. ALLEN, CLERK/REGISTER OF SE
III Section	
3. Miscellaneous S T R R T R T R T R T R T R T R T R T R	Compliance with ACT 345, P.A. 1990
Property in Sec. S T R	Anna
	APPROVED ON: 6-30.58 JS
4. Lot No Beronded Plus	OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
Recorded Plat	Contact EE
4. Lot No Recorded Plat b) o	OM + 1918 Register of Deeds Stamp & File Num
	A D 0
	1 T T F G H I J K I
1. Huston is warmen	2 5 5
I. <u>Huston K. Kerinedy</u> , in a field survey on <u>April 24</u> , 1998 o hereby s conformance with regulations and rules therefore as required in the corner manual of survey in that the corner points mentioned in lines 1 and 2 that the corner points mentioned in lines 1 and 2 that the corner points mentioned in lines 1.	3 - 1 - 1 - 1 - 2 - 1 - 1 - 2
conformance with regulations and rules therefore as required in the current manual of survey in that the corner points mentioned in lines 1 and 2 that the corner points mentioned in lines 1 and 2 that the corner points mentioned in lines 3, 4 and 5 above were in the current manual of survey in Board of Land Surveyors and lines 3, 4 and 5 above were in the current manual of surveyors.	state that under 4
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Land Surveyors or by a Decree of a Court of Law; established, re-established,	structions of the 5
recovered, found as expressed before of a Court of Law established	of the Michigan 6 18 17 16
	" " " " " " " " " " " " " " " " " " "
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	BLIGHT THE THE
on this certificate	20 + 21 + 22 + 23 + 24
range, may be recorded	9 <del></del>
	10-30-29-1
	11 26 - 25
A. Description of the	12-31-33
1917 Of a original monument and govern	33 - 35 - 35
1617-GLO Camentar in G. and duessoffes and/or subsequent	
1) 1007 L. Set Poet 16" Mary subsequent restora	tion:
<ul> <li>A. Description of original monument and accessories and/or subsequent restora 1817-GLO Carpenter, D.S.; Set Post 16" White Oak N62 ½°W 22 ½ I</li> <li>1.) 1997-Kemnitz, PS #16931; LCRC L.16887, Pg.010 – Fnd 3/8" Ren Description of corner evidence found and/or method applied in restoring or restoring.</li> </ul>	Links; 12" White Oak S77°E 71 Links od (I did not accpet this corner)
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing corner: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte the above existing monumentation the corner as
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing corner: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte the above existing monumentation the corner as
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing corner: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte the above existing monumentation the corner as
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02"44'52" West 13.73 feet of the actual corner. The corner	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing corner: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte the above existing monumentation the corner as
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing corner: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte the above existing monumentation the corner as
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02"44'52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte for of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G5 to F-3 GLO = 40.11 chains or 2647.26 Ft.	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte for of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monun on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52″ West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft.  G-5 to H-5 No GLO, corner fells in a landscaped in the solution of the corner fells in a landscaped global solution of the corner fells in a landscaped global solution of the corner fells in a landscaped global solution of the corner fells in a landscaped global solution of the corner fells in a landscaped global solution global	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte for of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monun on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 does not validate the location of the corner as recovered. Based upon the country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft.  2676.60 Ft. sidwell (Sec 16)  No plat or sidwell distances	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing corner:  a Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte in a solution of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monun on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02"44'52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft.  2676.60 Ft. sidwell (Sec 16)  G-5 to G-4  G-5 to G-4  G-5 to G-4  G-5 to G-4	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte for of plats, on page 30 of Oakland County Records, the above existing monumentation the comer as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 does not validate the location of the corner as recovered. Based upon the country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. 2676.60 Ft. sidwell (Sec 16)  G-5 to G-4 No GLO corner falls in Orchan No plat or sidwell distances	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monun on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 does not validate the location of the corner as recovered. Based upon the Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3  GLO = 40.11 chains or 2647.26 Ft.  2676.60 Ft. sidwell (Sec 16)  2676.31 Ft. (GPS-MEA)  G-5 to G-4  No GLO, corner falls in Orchard Lake No plat or sidwell distances	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monun on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52″ West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. 2676.60 Ft. sidwell (Sec 16) 2676.31 Ft. (GPS-MEA)  Description of corner falls in Orchard Lake No plat or sidwell distances	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monun on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52″ West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. 2676.60 Ft. sidwell (Sec 16) 2676.31 Ft. (GPS-MEA)  Description of corner falls in Orchard Lake No plat or sidwell distances	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monund on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the properties of the actual corner. The corner series from LCRC #1 were used to recover and verify the location of the corner falls in Orchard Lake No plat or sidwell (Sec 16)  Description of monument for corner and accessories established to perpetuate location of the corner by the location of the corner and accessories established to perpetuate location of the corner by the location of the corner by the location of the corner and accessories established to perpetuate location of the corner and location of the corner by the location of the corner and accessories established to perpetuate location of the corner by the location of the corner by the location of the corner by the location of the corner and loca	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Find a ½" Iron Rod wize for Orchard Lake Country Club. Based upon the existing monum does not validate the location of the corner as recovered. Based upon to recovered S02°44′52″ West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. 2676.80 Ft. sidwell (Sec 16) 2676.31 Ft. (GPS-MEA)  No GLO, corner falls in Orchard Lake No plat or sidwell distances  Description of monument for corner and accessories established to perpetuate loc N85°W 30.50′ NE corner of Orchard Lake Country Club.	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or read 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Find a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the second verify the location of the verification of the veri	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monum on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the survey states of the survey of the location of locat	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the fill be some sidwell distances.  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. 2676.60 Ft. sidwell (Sec 16) No plat or sidwell distances.  G-5 to G-4 No GLO, corner falls in Orchard Lake No plat or sidwell distances.  Description of monument for corner and accessories established to perpetuate loc G-5 I set a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland S41°W 43.00' East corner of Orchard Lake Country Club — Club House N13°F 62 20' Set Mag Nail & Remon Washer West for working or restoring or read a 1998 in Remon Washer West for working or read a 1998 in Remon Washer West for working or read a 1998 in Remonsion of the actual corner and accessories established to perpetuate loc S48E 49.00' Set Mag Nail & Remon Washer West for working or read a 1998 in Remon Washer West for working or read a 1998 in Remon Washer West for working or read a 1998 in Remon washer West for working or read a 1998 in Remon washer West for working or read a 1998 in Remon 1998 in Remon 1998 in Remonsion or read a 1998 in Remon Washer West for working or read a 1998 in Remonsion or read a 1998 in Remon 1998 in Remonsion or read a 1998 in Remonsion or remonsion or read a 1998 in Remonsion or remonsion or remonsion or read a 1998 in Remonsion or remon	Links; 12" White Oak S77°E 71 Links rod (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake of the found 1/2" Iron Rod, which I did not accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 — Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monund does not validate the location of the corner as recovered. Based upon the covered S02°44′52″ West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. No GLO, corner falls in Orchard 2676.60 Ft. sidwell (Sec 16) No plat or sidwell distances  Description of monument for corner and accessories established to perpetuate loc 36.5 I set a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland S41"W 43.00' East corner of Orchard Lake Country Club — Club House S48E 49.00' Set Mag Nail & Remon Washer West face 9" Locust S02°44'52" West 13.73 feet, found 12" Iron Rod Washer North face 12" Pine	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte of of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  The definition of the corner with the control of the found ½" Iron Rod, which I did not accept.  Surveyor Remonutarientation PS 1/823  Surveyor Remonutarientation PS 1/823  Surveyor Remonutarientation PS 1/823
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the corner falls in Orchard Lake No plat or sidwell distances  Description of monument for corner and accessories established to perpetuate location of the corner of Orchard Lake Country Club — Club House S48° was 13.73 feet. Found 12° location of the corner of Orchard Lake Country Club — Club House S48° 49.00' Set Mag Nail & Remon Washer West face 9° Locust S02°44'52" West 13.73 feet. found 12° location of the corner of 12° Pine	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte of of plats, on page 30 of Oakland County Records, the above existing monumentation the comer as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  The definition of the come with the comer accept.  Surveyor the position of the come with the comer accept.  Surveyor the position of the come with the comer accept.  Surveyor the county Remonutarientation in the comer accept.  Surveyor the county Remonutarientation is a county Remonutarientation in the comer accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 — Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monund does not validate the location of the corner as recovered. Based upon the covered S02°44′52″ West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of FIELD MEASURMENTS BETWEEN  G-5 to F-3 GLO = 40.11 chains or 2647.26 Ft. No GLO, corner falls in Orchard 2676.60 Ft. sidwell (Sec 16) No plat or sidwell distances  Description of monument for corner and accessories established to perpetuate loc 36.5 I set a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland S41"W 43.00' East corner of Orchard Lake Country Club — Club House S48E 49.00' Set Mag Nail & Remon Washer West face 9" Locust S02°44'52" West 13.73 feet, found 12" Iron Rod Washer North face 12" Pine	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte of of plats, on page 30 of Oakland County Records, the above existing monumentation the comer as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  The definition of the come with the comer accept.  Surveyor the position of the come with the comer accept.  Surveyor the position of the come with the comer accept.  Surveyor the county Remonutarientation in the comer accept.  Surveyor the county Remonutarientation is a county Remonutarientation in the comer accept.
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 — Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 or "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner Country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the corner falls in Orchard Lake No plat or sidwell distances  Description of monument for corner and accessories established to perpetuate location of the corner of Orchard Lake Country Club — Club House S48° 43.00° Set Mag Nail & Remon Washer West face 9" Locust S02°44'52" West 13.73 feet, found 12" Iron Rort 12" Pine	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte side of plats, on page 30 of Oakland County Records, the above existing monumentation the comer as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  The county Remonutarientation Dis 1000000000000000000000000000000000000
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52" West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the corner falls in Orchard Lake (GLO = 40.11 chains or 2647.26 Ft. No GLO, corner falls in Orchard 2676.31 Ft. (GPS-MEA)  Bescription of monument for corner and accessories established to perpetuate location of sidwell distances  Description of monument for corner and accessories established to perpetuate location of the corner of Orchard Lake Country Club — Club House S48E 49.00' Set Mag Nail & Remon Washer West face 9" Locust Naise 62.20' Set Mag Nail & Remon Washer North face 12" Pine selected location is accepted by me and is generally accepted by Profess description of the original corner.	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte side of plats, on page 30 of Oakland County Records, the above existing monumentation the comer as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  The county Remonutarientation Dis 1000000000000000000000000000000000000
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron on "ASSESSOR'S PLAT OF WEST SHORE" a plat recorded in Liber 5 recovered S02°44′52″ West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the corner as recovered. Based upon the country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the plat of the actual corner. The corner secovered S02°44′52″ West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the survey of the location of the corner secovered solves of the actual corner. The corner file in Orchard Lake S160 ft. S	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner)  establishing corner:  n Rod at ground surface on the East side of a club mentation as recovered along the base line as depicte in of plats, on page 30 of Oakland County Records, the above existing monumentation the corner as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  Id Lake  Cating the position of the corner it using the position of
B. Description of corner evidence found and/or method applied in restoring or real 1998-Kennedy Surveying, Inc. — Kennedy, PS #17623 - Fnd a ½" Iron house for Orchard Lake Country Club. Based upon the existing monum does not validate the location of the corner as recovered. Based upon to recovered S02°44′52" West 13.73 feet of the actual corner. The corner country Club is in a landscaped area.  Witnesses from LCRC #1 were used to recover and verify the location of the policy of the sidwell (Sec 16) No GLO, corner falls in Orchard Cafe No plat or sidwell distances  Description of monument for corner and accessories established to perpetuate for R45°W 30.50' NE corner of Orchard Lake Country Club — Club House S48E 49.00' Set Mag Nail & Remon Washer West face 9" Locust S02°44'52" West 13.73 feet, found ½" Iron Rod S02°44'52" West 13.73 feet, found ½" Iron Rod S02°44'52" West 13.73 feet, found ½" Iron Rod Selected Location is accepted by Profession of the original corner.	Links; 12" White Oak S77°E 71 Links od (I did not accept this corner) establishing comer: n Rod at ground surface on the East side of a club nentation as recovered along the base line as depicte 30 of plats, on page 30 of Oakland County Records, the above existing monumentation the comer as as recovered on the East side of Orchard Lake  of the found ½" Iron Rod, which I did not accept.  The county Remonutarientation DS 1/623  SURVEYOR 17023