Mar 23950 47300

10

MAY 1 F 1996

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

C	O	P	Y
---	---	---	---

Office Applications and	* * GD V *		· · · · · · · · · · · · · · · · · · ·			
for corners in	Filing Require	ement of Act 74, Mich. P.	.A. 1970 \$ 7.00 MISCELLANEOUS RECORDING			
Oakland (County)	Located In:	Corner Code ##	\$ 2.00 REMONUMENTATION 23 MAR 95 9:48 A.M. RECEIPT# 14B			
. Public Land Survey	т <u>4N</u> R <u>9E</u> т R	<u> </u>	PAID RECORDED - DAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS Compliance with ACT 345, P.A. 1990			
. December Constrailing	T R		APPROVED ON: 2-15-95  OAKLAND COUNTY REMONUMENTATION			
<ol> <li>Property Controlling in Section</li> </ol>	S T R S T R		PEER GROUP COMMITTEE			
I. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number			
	, Recorded Plat		A B C D E F G H I J K L			
i. Private Claims			2 6 5 4 3 2 1			
			3 + + + + + + + + + + + + + + + + + + +			

December 22 James J. Scharl, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Post set in 1817 G.L.O. survey; S 42°W 24 1ks, 14" W Oak; N 45°E 24 1ks, 12" W Oak.

LCRC, L7831, P322

Davis, 1980

Found 1" iron pipe

33.85 PK 12" tree 33.27 PK 8" tree ΝW

41.75' PK 14" quad tree SW

S 10°E 30.67' PK 12" triple tree

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No corner evidence was found. The area was cleared and regraded, destroying all witnesses referencing the corner. The corner was reestablished from monuments found in "Pine Knob Manor Homes" Condominium Subdivision Plan 245, L7293, P914-917, O.C. Records.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a concrete monument with O.C. remonumentation brass cap.

8.67' PK/remon tag W face 14" Oak N 10°E

N 85°E 16.55' PK/remon tag S face 14" Oak

S 15°E 51.40' NE corner hse #6918

Surveyor's Michigan License No.

S 25°W 63.00' NE corner gar. #6918

43.75' SW corner DE transformer

The selected location is a careful and faithful reestablishment of the position of the original corner. This corner is also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

Signed by _		ame	J. S. Q	nl_	Date	February 8,	1995	
	•		1					

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975** 

REVISED JAN., 1983