STATE OF HICHIGAN COUNTY OF OCEANA

LAND CORNER RECORDATION CERTIFICATE RECEIVED FOR RECORD Filing Requirement of Act 74, Mich. P.A. 1970 For corners in 3 DEC 1999 2:15:24 PM Oceana Located in: Comer Code # JOSEPH E. MERTEN REGISTER OF DEEDS 1. Public Land Survey T14NR 18W K-8 100955 2. Property Controlling R in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims I, J. Randolph Hepworth requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in in a field survey on May 20, 1999 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 5 NOTE: Not more than 2 corners, all in the same town and range, may be recorded А A. Description of original monument and accessories and/or subsequent restoration: K-8 1/4 CORNER COMMON TO SECTIONS 23 & 24 T14N, R18W BENONA TOWNSHIP GLO J. Mullett 1838 SET POST 10" Birch South (7 ks) 4.6' Book A, Pg 30; H Hawley, 1877; "Running thence N3°25'W 2655' (40ch 23lks) to the quarter section post on west side of section corner as follows: large course boulder stone with one small boulder underneath and hemlock stake on north side." Stone previously set for post." Oceana County Removamestation Unrecorded Survey, JR Hepworth #26457, 11/17/86 Set 1/2" X 2" IR C/L N-S Road W 18" Paer Group Period & Approved Date: 11-11-99 6" Willow 20" Maple 224°az 140°az 14.69 118,85 N end 24" CMP 305°az 49.7 1LK B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. J. Randolph Hepworth Oceana County Surveyor I found a JRH 1/2" Iron as set in 1986. The centerline of N-S road is 18' west; centerline of road to the west is 18' north. No occupation is visible to the east. Area is in transition of fill and cut on the west side of a curving stream ravine. Road alignment is such that avoids the stream ravine. The road to the west was probably re-cut when the N-S road was reconstructed many years ago. It is doubtful to me whether excavation by backhoe would be fruitful in This Iron was re-established by me in 1986 using the Grant, 1893, survey; various ties to 1/16 line fence, 1/4 line fence, and ancient road ties. Specifically, the easting location was determined by distance from the N-S 1/4 Line ancient fence to the E 1/16 line ancient fence (comparison with Grant, 1893= 1314.0°; JRH, 1986=1309.5°) and then measuring East to the section line. The northing location was determined by producing a straight line from east section line. This position is confirmed by fence tie to interior 1/16 line fence corpors in Section 23. I accept the JRH 1/2" Iron as a careful and faithful re-establishment of the position of the original corner. No evidence is known to me that would lead me C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" above the JRH 1/2" Iron which was driven down 60d spk 60d spk 60d spk N Face 38°az 64.42' 56.74' TE of MIC 4" Cherry EDM 60d spk 260°az SE Face 24" Maple EDM chiseled notch 216°az N. End 118.74 CMP culvert EDM 303°az

49.83

Darl

26457

Signed by

Surveyor's Michigan License No.

EDM

Date

RVEYORS FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28

199

November 30,

REVISED MAY 14,1973 REVISED JAN, 1983 REVISED OCT., 1995

i eesoesii

HEP ETCHH

LAND

SURVEYOR

No.

ತಾಲ