

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

MAR 02 2001

SECTION

For corners in

Ontonagon County Located in: Corner Code #

- | | | |
|------------------------------------|-----------|--------|
| 1. Public Land Survey | T48N R39W | K - 12 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

JUDITH D. ROEHM 1P
Ontonagon County
Page 1 of 1 LC 5/369
JEM Date 01/03/2001 Time 14:39:16
RECORDING FEE: 9.00

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Joseph C. Domitrovich, in a field survey on September 12, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K - 12) 1/4 Corner Common to Sections 35 & 36, T48N, R39W.

1851 - Artemis Curtis Set 1/4 post with ties:

16" Sugar	N 54°E	26 links
12" Sugar	S 50°W	20 links

I found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. There is a fence intersection and an iron pipe near the 1/4 corner position but I did not accept them. I re-established the corner position by single proportionate measurement. This position falls 19.7' west and 17.7' north of a 5/8" iron pipe and 36.6' west and 17.3' north of an old fence intersection. I Monumented the single proportionate position as the best representation of the true 1/4 corner position.

Research on file with County Remonumentation Representative.

DEED GROUP APPROVED

Earl W. Applekamp
COUNTY CLERK

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 12-19-00

Corner is a 2 1/2" x 30" aluminum pipe with a 3" diameter cap stamped to read: COUNTY REMONUMENTATION; T48N, R39W; 1/4; S. 35, S. 36; 2000; P.S. 37273. Ties:

8" Hard Maple	N 38°E	7.92'
6" Hard Maple	S 55°E	19.41'
5/8" iron pipe	S 48°E	26.45'
8" Basswood	S 14°W	13.40'
5" Hard Maple	N 37°W	9.86'
Steel Sign Rail	North	0.83' (to face)



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by *J. C. Domitrovich*

Date 12/19/00

Surveyor's Michigan License No. 37273