NOV 1 6 1998

## LAND CORNER RECORDATION CERTIFICATE

SECTION  Filing Requirement of Act 74, Mich. P.A. 1970	
For corners in	APRONCE
Osceola Located In: Corner Code #	APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County
1. Public Land Survey T_19N R 9W	Markewall
2. Property Controlling S T R	July 78
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	A E C D E P G H I J K L M
I, <u>Craig W. McVean</u> , in a field survey on <u>Oct. 7</u> 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	2 6 5 4 3 2 1 3 4 7 8 9 -10 11 -12 5 6 -18 -17 -16 -15 -14 -13 7 7 8 -19 -20 -21 -22 -23 -24 -
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	110-30-29-28-27-26-25-
A. Description of original monument and accessories and/or subsequent restoration:	12 31 32 33 34 35 36
3-13 - GLO - Set 1/4 Post - J. Hodgson - 1837 Beech 12" N42°E 22L. Hemlock 14" N38°w 18L A.O. Temple - 1892 - FND. Beech Stp. 12" N42°E 22L. and Hem. 14" N38°W 18L. was down Set 4' Iron in 3' of 3" Dia. tile. Pine Stp. 36" N82°E 40L. Pine Stp. 36" N2.5°W 40L LCRC - L.1 P. 285 - K.J. Ostling − 1972 FND. Temple Mon. & Remains of Wit. Stp. Left 1/2" bar in 3" tile, in place. Added Cedar Post. E-W FN. Remains Due S 33' ± 3' 14" Maple S53°W 93.8'	OSCEOLA COUNTY REGISTER OF DEEDS 98 OCT 21 PH 4: 14
B. Description of corner evidence found and/or method applied in restoring or reestablishing corn	
J-13 - Standard 1/4 Corner Common to Sec. 35, T19N, R9W - FND. 1/2" Iron Rod in 3" Dia. Brown. CL. of 10' wide N-S Sand Rd. is 100' ± E. Monument accepted as a careful and faithful perpe	Vit. Tile per Temple and Ostling. tuation of the position of the original
C. Description of monument for corner and accessories established to perpetuate locating the positive description of monument for corner and accessories established to perpetuate locating the positive description of monument for corner and accessories established to perpetuate locating the positive description of monument for corner and accessories established to perpetuate locating the positive description of monument for corner and accessories established to perpetuate locating the positive description of monument for corner and accessories established to perpetuate locating the positive description descripti	
J-13 - Drove 1" x 48" Iron Pipe with 4" DNR Alum. Cap over 1/2" Iron Rod in Tite. Built Ring of Stone Cedar Guard Post on NW Side.  N76°E 28.25' to set Spike in CL. Remains 36" Pine Stp. (AOT) N1°W 28.26' to set Spike in CL. Remains 36" Pine Stp. (AOT) S53°W 93.96' to set N&T in S. Side Tw. 16" R. Maple - scribed 'NBT' (KJO) S27°E 18.64' to set N&T in E. Side 5" R. Oak - scribed 'NBT' N74°E 29.94' to set N&T in N. Side 8" R. Maple - scribed 'NBT' N37°W 31.62' to set N&T in E. Side 6" R. Maple - scribed 'NBT' West 26.28' to J-1, T18N,R9W	CRAIG W. McVEAM. PROFESSIONAL. SURVEYOR No. 39088
Signed by Crain M. Ma June 101	OFESSION PLANT
Surveyor's Michigan License No. 39088 Date 10/	21/1998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995