LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	_ Located In:	Corner Code #								
1. Public Land Survey	T 51N R 37W T R	F11								
2. Property Controlling in Section	S T R S T R							39		
3. Miscellaneous Property in Sec.	S T R S T R		Pa	gister of I	Joods	Ctom	. P Eil	o Niver	-b	
4. Lot No. , Red 5. Private Claims	corded Plat		1 A B 2 - 6	C D	E	F G	R -3-	I J		L I
	74, Michigan P.A. of 1970, the corner	points mentioned in lines 1 and 2		- 8		3-1	_ _10_		-	-12-
instructions of the United States [a Court of Law and /or that the or	regulations and rules therefore as requi Department of the Interior, Bureau of 9 orner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	Land Management or by a decree of ad 5 above were in conformance with	6 —18	17		16	-15-			-13-
re-established, monumented, recove	ered, found as expressed below: ers, all in the same town and range		9 10 30	29		28	-22- -27-	1 2°3	5	-24
on this certificate.			11 12 31-	32		333	-34-	35		-36-
 A. Description of original me 	nnument and accessories and/or	subsequent restorations								

(F11) Quarter corner common to Sections 28-33. 1846 - Established by S.W.Higgins Deputy Surveyor, midway and on the Section line between Section corners 40.05 chains east and west. Set post. Cedar 10 N71W 4 links, Hemlock 8 S45E 12 links. Ca. 1907-1910 Corner shown on old mining company survey drawing, probably a result of surveys by W.B.Smith and/or Engineers Fesing and Gibbs. The drawing shows the corner (monument description not noted) midway and on a straight line between Section corners 2652.4' easterly and westerly, the bearing of the Section line being N87 deg. 28'W. 1/16 corner #2, Section 33 is also shown, midway between Section and Quarter corners. The drawing, or a copy of it, resides at the offices of Steven Hein PS, Laurium, MI. 1980 - Reestablished by K.L.Sackett RLS "at spot of old section subdivision of 1900. Reestablished by projecting line from section corner across 1/16 corner and double the distance". Set 1"IDx30" I.pipe with 4" alum. cap. 5" Elm N36E 41.5', 4" Maple N60W 13.0', 8" Balsam S40E 28.1'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F11) Found the 1980 monument in good condition, at the record position, and at record bearing and distance from the remaining two 1980 NBTs. The Balsam SE and Maple NW are in good condition, with old blazes visible. Bearings and distances to adjacent Section corners were found to be N87 deg. 18'23"W 2652.84' and S87 deg. 31'45"E 2651.00' (true bearings). This position also checks with 1/16 corners #2 and #5, Section 33, both shown on the mining company survey drawing. I accept the monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F11) Found 1"ID I.pipe with 4" alum. MDNR cap stamped to identify the corner. Set measuring nail with MDNR tag in the side of: 9" Balsam S36E 28.3' old blazes (1980 NBT) 6" Maple in clump N58W 13.2' do 12" W.Spruce N71E 21.5' mrkd "1/4S NBT"

4" Sugar S27W 12.7'

Set cedar post adjacent. Bearings magnetic.

33986

Date 09/07/2010

Signed by

Surveyor's Michigan License No.

For the Michigan Department of Natural Resources and Environment, Forest Management Division

STEPHAN J

SZYSZKOSKI LAND

JRVEYOR

4 at p.