JUDITH D. ROEHM 11/19/96 Ontonason County 12:51 LC 4/ 233 JEM Fee: 9.00 Page 1 of 1

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		, and the state of	1
Ontonagon (County)	Located In:	Corner Code #	
1. Public Land Survey	T_51N R_40W T R T R	#003	SURVEY & REMONUMENTATION
Property Controlling in Section	TR S T:_ R S T R	· ·	MAY 2 2 1997
3. Miscellaneous	S TR		COMMISSION
Property in Sec.	S TR		Register of Deeds Stamp & File Number
4. Lot No, Recor	ded Plat		<b>.</b>
5. Private Claims	<u> </u>		A B C D E F G H I J K I
			2 6 5 4 4 2 2
Lacort C Domitrovich	in a fall annual Conform	hor 20 40 95	3
requirements of P.A. 74, Michiga	, in a new survey on <u>septem</u> in P.A. of 1970, the corner points	ber 30, 19 96 do hereby state that und mentioned in lines 1 and 2 above were	sin
conformance with regulations and	rules therefore as required in the	current manual of survey instructions of t	the 5
that the corner points mentioned	menor, Bureau of Land Managem in lines 3, 4 and 5 above were in a	ent or by a decree of a Court of Law and conformance with the rules of the Michig	
	a Decree of a Court of Law; of	established, re-established, monumente	ed, /
recovered, round as expressed be	KJW,		8 19 20 21 22 23 2
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9
on this certificate.			10 30 29 28 27 26 2
			11
(E-1/2) Meander Corner co	mmon to Sections 4 and 5	5. T51N, R40W	12 31 32 33 34 35 3
A. Description of original mod		•	13
14" W. Pine S 7 - Supervisor's Plat of of the E 1/4 Corner 1941 - Supervisor's Floods 1784.90' North of the corner of Section 5 1969 - M.S.H.D. for M-64 I indicate anything a	750 E 29 links If Gov't Lots 1 & 2, Section If Section 5, Wood Pat of NW 1/4 of Se The E 1/4 corner of Section If Highway plans show concit the Meander Corner.	ection 4, T51N, R40W, shows a 5, and a concrete monument a	nument on the section line 1825.05' north a concrete monument on the section line at the 1/16 corner 1320' north of the E 1/4 corner and the 1/16 corner. They do not
Original Meander Corner a	nd accessories have beer	n destroyed by shoreline erosic	on. I found a 3/4" iron pin at the shoreline.
I recovered the 1/16 corner	and E 1/4 corner as calle	ed for in Floodwood Plat and Hi noved from their original position	ighway plans. Additional work in Floodwoo
the plat monuments for the	section line. I established		rood Plat. I did not accept the pin, and held nder corner on this section line 171.55' south
	·	·	PEER GROUP APPROVED
Research on file with Coun	ty Remonumentation Rep	resentative.	COUNTY BETTE SENTATIVE
C. Description of monument	for comer and accessories es	stablished to perpetuate locating the	
Corner is a 3/4" x 72" alumi	inum rod with a 3" diamete	* = = =	ead: W.C.M.C; S.4, S.5; T.51N., R,40W.;
1/16 corner	S 01 <sup>0</sup> 13' 04" E	400.00' (Concrete Monum	
E 1/4 Corner Section 5	S 01 <sup>0</sup> 13' 04" E	1721.48' (Concrete Monu	
5" Soft Maple	\$ 58 <sup>0</sup> E	11.38'	
8" Poplar Steel Sign Post	S 48 <sup>0</sup> W S 54 <sup>0</sup> W	21,23' 14.21'	DOSEPH DOMITROVICH
Steel Sign Post 6" Soft Maple	N 78 <sup>0</sup> W	14.21 12.56'	本 LAND A SURVEYOR
3/4" Iron Pin	West	20.48'	No.
		ail in side of witness objects un	less noted 37273   6

Signed by ALC. Jon: Fin Low Surveyor's Michigan License No. 37273

Date 11/10/96